

Errata Sheet

SALP Board Report No. 50-528/85-36, 50-529/85-38 and 50-530/85-28

Part III SUMMARY OF RESULTS

Functional Area 18, Preoperational Testing  
Page 3

Now Reads:

<u>Functional Areas</u>	<u>Last SALP Period Rating</u>	<u>This SALP Period Rating</u>	<u>Trend*</u>
18. Preoperational Testing	3	2	Not Apparent"

Should Read:

<u>Functional Areas</u>	<u>Last SALP Period Rating</u>	<u>This SALP Period Rating</u>	<u>Trend</u>
18. Preoperational Testing	3	1	Improved"

Basis:

This is an editorial error in the summary table. The evaluation detail in pages 27 and 28 show Category 1 rating and steadily improved performance during the assessment period. Therefore, the summary table is revised to reflect the evaluation detail.

B605070108 B60422  
PDR ADOCK 05000528  
G PDR

### III. SUMMARY OF RESULTS

Overall, the SALP Board found the licensee's performance to be acceptable and directed toward safe facility operation. The Board identified strength or improvements in the areas of operator's response to unusual plant conditions, fire protection systems, and preoperational testing. However, performance should be improved in the areas of surveillance, emergency preparedness, security, and subcontractor quality assurance, due to observed weaknesses or a declining trend.

<u>Functional Areas</u>	<u>Last SALP Period Rating</u>	<u>This SALP Period Rating</u>	<u>Trend*</u>
1. Plant Operations	2	2	Improved
2. Radiological Controls	2	2	Not Apparent
3. Maintenance	2	2	Improved
4. Surveillance	None	2	Not Apparent
5. Fire Protection	None	1	Not Apparent
6. Emergency Preparedness	1	2	Declined**
7. Security	2	2	Improved
8. Refueling	None	1	None
9. Quality Program and Administration Controls	None	2***	Not Apparent
10. Licensing Activities	2	2	Not Apparent
11. Training	None	2	Not Apparent
12. Containment Safety-Related Structures, and Major Steel Supports	2	2	Not Apparent
13. Piping Systems and Supports	2	2	Not Apparent
14. Safety-Related Components	2	2	Not Apparent
15. Auxiliary Systems	2	2	Not Apparent
16. Electrical Equipment and Cables	2	2	Not Apparent
17. Instrumentation	1	1	Not Apparent
18. Preoperational Testing	3	2	Not Apparent
19. Startup Testing	3	2	Not Apparent

\* The trend indicates the SALP Board's perception of the trend of the licensee's performance during the current assessment period. It is not necessarily a comparison of performance during the current period with the previous period. For example, performance in the fire protection area was considered to be improving, even though performance in this functional area was not assessed during the previous SALP period.

\*\* While an overall decline between rating periods was observed, an improvement in performance was noted toward the end of this appraisal period.

\*\*\* This area was considered by the Board to be a marginal Category 2 rating, with significant deficiencies.

ORIGINAL PAGE

### III. SUMMARY OF RESULTS

Overall, the SALP Board found the licensee's performance to be acceptable and directed toward safe facility operation. The Board identified strength or improvements in the areas of operator's response to unusual plant conditions, fire protection systems, and preoperational testing. However, performance should be improved in the areas of surveillance, emergency preparedness, security, and subcontractor quality assurance, due to observed weaknesses or a declining trend.

<u>Functional Areas</u>	<u>Last SALP Period Rating</u>	<u>This SALP Period Rating</u>	<u>Trend*</u>
1. Plant Operations	2	2	Improved
2. Radiological Controls	2	2	Not Apparent
3. Maintenance	2	2	Improved
4. Surveillance	None	2	Not Apparent
5. Fire Protection	None	1	Not Apparent
6. Emergency Preparedness	1	2	Declined**
7. Security	2	2	Improved
8. Refueling	None	1	None
9. Quality Program and Administration Controls	None	2***	Not Apparent
10. Licensing Activities	2	2	Not Apparent
11. Training	None	2	Not Apparent
12. Containment Safety- Related Structures, and Major Steel Supports	2	2	Not Apparent
13. Piping Systems and Supports	2	2	Not Apparent
14. Safety-Related Components	2	2	Not Apparent
15. Auxiliary Systems	2	2	Not Apparent
16. Electrical Equipment and Cables	2	2	Not Apparent
17. Instrumentation	1	1	Not Apparent
18. Preoperational Testing	3	1	Improved
19. Startup Testing	3	2	Not Apparent

\* The trend indicates the SALP Board's perception of the trend of the licensee's performance during the current assessment period. It is not necessarily a comparison of performance during the current period with the previous period. For example, performance in the fire protection area was considered to be improving, even though performance in this functional area was not assessed during the previous SALP period.

\*\* While an overall decline between rating periods was observed, an improvement in performance was noted toward the end of this appraisal period.

\*\*\* This area was considered by the Board to be a marginal Category 2 rating, with significant deficiencies.

CORRECTED PAGE