Mr. John K. Wood Vice President - Nuclear Davis-Besse Nuclear Power Station Centerior Service Company 5501 North State Route 2 Oak Harbor, OH 43449

SUBJECT: NOTICE OF VIOLATION (NRC INSPECTION REPORT 50-346/98301(OL))

Dear Mr. Wood:

This will acknowledge receipt of your letter dated October 21, 1998, in response to our letter dated September 23, 1998, transmitting a Notice of Violation associated with examination development at the Davis Besse Nuclear Power Plant. The effectiveness of your corrective actions will be reviewed following submittal of your root cause investigation results.

Sincerely,

Original Signed by Steven A. Reynolds (for)

John A. Grobe, Director Division of Reactor Safety

Docket No.: 50-346 License No.: NPF-3

Enclosure: Ltr dtd 10/21/98 O. Kingsley

Davis Besse to USNRC

See Attached Distribution

DOCUMENT NAME: G:DRS\DAV98301.WPD

OFFICE	RIII	c	RIII	N	RIII	IN	RIII	N
NAME	Biebly HNGA		Leach oyne		Kozak 7		Grobe &	
DATE	11/6/98		11/6/98		11/4/98		11/9/98	

OFFICIAL RECORD COPY

cc w/o encl:

J. Stetz, Senior Vice President - Nuclear

J. Lash, Plant Manager

J. Freels, Manager, Regulatory Affairs

M. O'Reilly, FirstEnergy

State Liaison Officer, State of Ohio

cc w/encl:

R. Owen, Ohio Department of Health

C. Glazer, State of Ohio Public

**Utilities Commission** 

## Distribution:

RPC (E-Mail)

Project Mgr., NRR w/o encl

J. Caldwell, RIII w/o encl

C. Pederson, Rill w/o encl

B. Clayton, RIII w/o encl

SRI Davis-Besse w/o encl

DRP w/o encl

TSS w/o encl

DRS (2) w/o encl

RIII PRR w/o encl

PUBLIC IE-42 w/o encl

Docket File w/o encl

**GREENS** 

IEO (E-Mail)

DOCDESK (E-Mail)

M. Bies, RIII w/o encl



**FirstEnergy** 

Davis-Besse Nuclear Power Station 5501 North State Route 2 Oak Harbor, Ohio 43449-9760

John K. Wood Vice President - Nuclear 419-249-2300 Fax: 419-321-8337

Docket Number 50-346

License Number NPF-3

Serial Number 1-1175

October 21, 1998

Mr. J. L. Caldwell
Acting Regional Administrator, Region III
United States Nuclear Regulatory Commission
801 Warrenville Road
Lisle, Illinois 60532-4351

Subject: Response to Operator Licensing Examination Report 50-346/98301(OL)

Dear Mr. Caldwell:

The Davis-Besse Nuclear Power Station has received Operator Licensing Examination Report 50-346/98301 (OL), Toledo Edison Log Number 1-4010. This report documented the results of the Senior Reactor Operator (SRO) examinations administered the week of August 3, 1998, and the concurrent operations inspection. This SRO written examination was prepared and administered in accordance with the guidelines provided in NUREG-1021, Operator Licensing Examination Standards for Power Reactors, Interim Revision 8, dated January, 1997.

Hach

After the examination was administered, seven examination questions were required to be deleted or answers changed as a result of post written examination comments. This exceeded the five percent criteria stated in Section ES-501 C.2.c of NUREG-1021. A Potential Condition Adverse to Quality Report (PCAQR) was initiated on August 10, 1998, to investigate the cause of this occurrence and determine corrective actions to improve future operator license written examinations.

The root cause investigation is in progress at this time and is considering the exam preparation process. This SRO examination was the first prepared in accordance with the guidelines of NUREG-1021, Interim Revision 8. Preparation of this examination was potentially impacted by a change of personnel responsible for reviewing and approving the examination. As documented

Docket Number 50-346 License Number NPF-3 Serial 1-1175 Page 2

in this examination report, a significant number of examination questions, approximately 50 percent, had to be changed after the initial review. Due to this large number of required changes, the examination validation process may have been impacted. This root cause investigation is continuing and will be completed by February 23, 1999. The Nuclear Regulatory Commission will then be provided the root cause and corrective actions.

Requalification examinations are currently being administered to licensed operators. Due to the differences in the examination development and review process for the requalification exam versus the SRO exam just completed, the type of deficiencies encountered in the initial SRO exam should not occur.

Should you have additional questions or require additional information, please contact Mr. James L. Freels, Manager - Regulatory Affairs, at (419) 321-8466.

Sincerely yours,

DLM/dlc

cc: A. G. Hansen, NRC Project Manager S. J. Campbell, DB-1 Senior Resident Inspector USNRC Document Control Desk Utility Radiological Safety Board