

JUN 08 1988

Yellow

Docket Nos. 50-348, 50-364
License Nos. NPF-2 and NPF-8

Alabama Power Company
ATTN: Mr. R. P. McDonald
Senior Vice President
P. O. Box 2641
Birmingham, AL 35291-0400

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-348/88-16 AND 50-364/88-16

The above subject inspection report was transmitted to you by letter dated May 19, 1988. As a result of a telephone conversation held between D. Jones of your staff and N. Merriweather of NRC, Region II, on June 6, 1988, it has come to our attention that Appendix A to the report: 1) incorrectly references ASCO solenoid valves N11SV3976A-B/B-B as normally energized valves during a design basis accident, 2) incorrectly identifies valve no. N23SV3227CA-A as N23SV3226CA-A, and 3) incorrectly identifies valve no B31SV0444BB-B as valve no. B31SV0444BA-A. The appendix has been revised with the above changes and is enclosed. Please delete the superseded page and insert the corrected page in your copy of the report.

Should you have any questions concerning this letter, please contact us.

Sincerely,

151

Alan R. Herdt, Chief
Engineering Branch
Division of Reactor Safety

Enclosure:
Corrected Appendix A to Inspection
Report Nos. 50-348/88-16 and
50-364/88-16

cc w/encl:

- ✓ B. M. Guthrie, Executive Vice President
- ✓ J. D. Woodard, General Manager -
Nuclear Plant
- ✓ W. G. Hairston, III, Vice President -
Nuclear Support
- ✓ J. W. McGowan, Manager-Safety Audit
and Engineering Review
- ✓ S. Fulmer, Supervisor-Safety
Audit and Engineering Review

bcc w/encl: (See page 2)

8806210176 880608
PDR ADOCK 05000348
Q PDR

11
1601

JUN 08 1988

Alabama Power Company

2

bcc w/encl:
✓ NRC Resident Inspector
DRS Technical Assistant
✓ E. Reeves, Project Manager, NRR
Document Control Desk
State of Alabama

RII 

NMerriweather:gb
06/4/88

RII 

TConlon
06/4/88