

Northeast Nuclear Energy

Rope Ferry Rd. (Route 156), Waterford, CT 06385

Millstone Nuclear Power Station
Northeast Nuclear Energy Company
P.O. Box 128
Waterford, CT 06385-0128
(860) 447-1791
Fax (860) 444-4277

The Northeast Utilities System

NOV 4 1998

Docket No. 50-336
B17508

Re: 10 CFR 50.73(a)(2)(v)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Millstone Nuclear Power Station Unit 2
Licensee Event Report 97-037-01
Service Water Piping Liner Material Peeled Off and Lodged in the
Strainer for the Emergency Diesel Generator Heat Exchanger
Causing Reduced Flow to the Heat Exchangers


This letter forwards Supplement 1 to Licensee Event Report (LER) 97-037, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2, on November 26, 1997. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(v). This LER supplement provides conclusions from the inspections and repairs conducted in response to this event.

The are no new commitments contained within this letter.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

FOR: J. A. Price
Director - Millstone Unit No. 2

BY: 
John T. Swintoniewski
Assistant Unit Director
Millstone Unit No. 2

9811180176 981104
PDR ADOCK 05000336
S PDR

cc: See Page 2

170169

IE 22

U.S. Nuclear Regulatory Commission
B17508\Page 2

Attachments: 1. LER 97-037-01

cc: H. J. Miller, Region I Administrator
D. G. McDonald, Jr., NRC Senior Project Manager, Millstone Unit No. 2
D. P. Beaulieu, Senior Resident Inspector, Millstone Unit No. 2
E. V. Imbro, Director, Millstone ICAVP Inspections
S. Dembek, NRC Project Manager, Millstone Unit No. 1

Docket No. 50-336
B17508

Attachment 1

Millstone Nuclear Power Station, Unit No. 2

Licensee Event Report 97-037-01

November 1998