

Entergy Operations, Inc.
P.O. Box B
Killona, LA 70066
Tel 504 739 6242

Early C. Ewing, III
Director
Nuclear Safety & Regulatory Affairs
Waterford 3

W3F1-99-0082
A4.05
PR

May 14, 1999


U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Subject: Waterford 3 SES
Docket No. 50-382
License No. NPF-38
Reporting of Licensee Event Report

Gentlemen:

Attached is Licensee Event Report (LER) 99-004-00 for Waterford Steam Electric Station, Unit 3. This report provides details of the discovery that response time testing had not been performed for the Engineered Safety Features Actuation System containment cooling function as prescribed by Technical Specification Surveillance Requirement 4.3.2.3. This condition constituted a missed surveillance and is being reported pursuant to 10CFR50.73(a)(2)(i)(B).

Very truly yours,

 (for E.C. Ewing)

E.C. Ewing
Director,
Nuclear Safety & Regulatory Affairs

ECE/ALL/ssf
Attachment

cc: E.W. Merschoff (NRC Region IV), C.P. Patel (NRC-NRR),
A.L. Garibaldi, P. Lewis - INPO Records Center,
J. Smith, N.S. Reynolds, NRC Resident Inspectors Office,
Administrator - LRPD

9905210133 990514
PDR ADOCK 05000382
S PDR

1/1
IE22