

Farley #1

NRC FORM 304
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

DCS-

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 00

CONT

REPORT SOURCE

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 00

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 00

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 00

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 00

NAME OF PREPARED W. G. Hainston, III

PHONE (205) 899-5156

B511120034 B30404
PDR ADOCK 05000364
S PDR

FE22 V1
83 retrof +

Licensee Event Report
LER No. 83-613/03L-0
Page 2 of 2

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONTINUED)

The second occurrence was attributed to a blown fuse. No cause for the blown fuse could be determined. The fuse was replaced and following the performance of FNP-2-STP-5.0, the rod control system was declared operable at 0915 on 3/28/83. No common cause for these occurrences could be derived since the problems originated in different power cabinets.

Mailing Address
Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291
Telephone 205 783-6081

F. L. Clayton, Jr.
Senior Vice President
Flintridge Building

Alabama Power

The Southern Electric System

April 4, 1983

Docket No. 348
Docket No. 364

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, N.W.
Suite 3100
Atlanta, Georgia 30303

RMW
SAH

0000631A04

LER
LER # <u>364-83019</u>
EVENT DATE <u>830307</u>
INPO RCVD DATE <u>830411</u>
NSAC RCVD DATE _____

Dear Sir:

Joseph M. Farley Nuclear Plant, Unit 1, Licensee Event Reports Nos. LER 83-009/03L-0 and LER 83-010/03L-0 and Unit 2, Licensee Event Report No. LER 83-013/03L-0 are forwarded with three (3) copies of each in accordance with FNP Technical Specification 6.9.1.13 to provide thirty (30) days written notification of the occurrence.

If you have any questions, please advise.

Yours very truly,

F. L. Clayton, Jr.
F. L. Clayton, Jr.

FLCJr/KWM:nac

Enclosures

xc: Director, IE (30 copies)
Director, MIPC (3 copies)

bc: Mr. J. M. Farley
Mr. W. O. Whitt
Mr. S. E. Bradley
Mr. W. H. Bradford
Mr. R. P. McDonald
Mr. H. O. Thrash
Mr. O. D. Kingsley, Jr.
Mr. J. W. McGowan
Mr. D. S. Mask
Mr. W. G. Hairston, III.
Mr. Lee Williams
Mr. W. G. Ware
INPO Records Center
File: 91A3.01/F-6

IE22
43
RETROFIT