



Boston Edison
Pilgrim Nuclear Power Station
Rocky Hill Road
Plymouth, Massachusetts 02360

L.J. Olivier
Vice President Nuclear and Station Director

December 4, 1997
BECo Ltr. 2.97. 122

U.S. Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, D.C. 20555


Docket No. 50-293
License No. DPR-35

The enclosed Licensee Event Report (LER) 97-016-00, "Recirculation System Loop 'B' Pump Trip due to Surveillance Procedure Inadequacy," is submitted in accordance with 10 CFR Part 50.73.

This letter contains the following commitment(s):

- The surveillance procedure for initiating the 'B' emergency diesel generator will be revised to include the status of additional relays prior to resetting the logic circuitry.
- Complete a review of all logic system functional test procedures for similar improvement.

Please do not hesitate to contact me if there are any questions regarding this report.


L. J. Olivier

DWE/9701600.doc

Enclosure: LER 97-016-00

cc: Mr. Hubert J. Miller
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

IEDD

Sr. NRC Resident Inspector - Pilgrim Station

Standard BECo LER Distribution

9712100282 971204
PDR ADOCK 05000293
S PDR

