



Point Beach Nuclear Plant
6610 Nuclear Rd., Two Rivers, WI 54241

(920) 755-2321

NPL 99-0073

February 4, 1999

Document Control Desk
U.S. NUCLEAR REGULATORY COMMISSION
Mail Station P1-137
Washington, D.C. 20555

10 CFR 50.73

Ladies/Gentlemen:

DOCKET NO. 50-266
LICENSEE EVENT REPORT 1999-001-00
SAFETY INJECTION RECIRCULATION LINE TO
REFUELING WATER STORAGE TANK FROZEN
POINT BEACH NUCLEAR PLANT, UNIT 1

Enclosed is Licensee Event Report 1999-001-00 for the Point Beach Nuclear Plant, Unit 1. This report is provided in accordance with 10 CFR 50.73(a)(2)(ii)(B), as, "Any event or condition that resulted in the nuclear plant being in a condition that was outside the design basis of the plant." This report describes the discovery that the common minimum recirculation flow line return to the refueling water storage tank (RWST) for the safety injection and containment spray pumps was partially frozen and would not pass flow as a result of a failure of the freeze protection heat tracing for this piping.

New commitments within this report are indicated in italics.

Please contact me if you require additional information.

Sincerely,

Richard G. Mende
Plant Manager
Point Beach Nuclear Plant

CWK/tat

Enclosure

cc: NRC Resident Inspector
NRC Regional Administrator
PS:W
INPO Support Services

9902100324 990204
PDR ADOCK 05000266
S PDR

1/1
IE22