



An Illinova Company

Illinois Power Company
P.O. Box 678
Clinton, IL 61727
Tel 217 935-8881 x3900
Fax 217 935-4632

John P. McElwain
Chief Nuclear Officer

U-603157
2C.220

February 11, 1999

Docket No. 50-461

10CFR50.73

Document Control Desk
Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: Clinton Power Station - Unit 1
Licensee Event Report No. 1998-036-01

Dear Madam or Sir:

Enclosed is Licensee Event Report (LER) No. 1998-036-01: Opening Incorrect Electrical Cubicle Causes Loss of Shutdown Cooling and Leads to Failure to Meet Technical Specification Required Action in the Required Time. This report contains revised Description of Event, Cause and Corrective Action sections. This report is being submitted in accordance with the requirements of 10CFR50.73.

The enclosed report contains the following commitments:

- Training will be provided to licensed operators reinforcing management expectations regarding Technical Specification compliance. Specifically, the importance of meeting Technical Specification Action time limits, and ensuring adequate crew focus necessary to be successful will be stressed.
- CPS procedure 3312.03 will be revised to provide alternate means for ensuring adequate system fill and vent prior to restoration, and to allow restoration of a RHR loop previously aligned to the suppression pool without performing a piping flush when necessary to meet Technical Specification reactor coolant circulation requirements.

Sincerely yours,

John P. McElwain
Chief Nuclear Officer

170057

MRS/krk

9902170300 990211
PDR ADOCK 05000461
S PDR

11
1622

Enclosure

cc: NRC Clinton Licensing Project Manager
NRC Resident Office, V-690
Acting Regional Administrator, Region III, USNRC
Illinois Department of Nuclear Safety
INPO Records Center