SMB

AUG 0 1 1986

Docket No. 50-305

Wisconsin Public Service Corporation ATTN: Mr. D. C. Hintz Manager Nuclear Power Post Office Box 19002 Green Bay, WI 54307-9002

Gentlemen:

The preliminary review of your initial response to IE Bulletin 85-03 "Motor-Operated Valve Common Mode Failures During Plant Transients Due To Improper Switch Settings" indicates that it does not contain a description of the program to assure valve operability as requested by Action Item e of the Bulletin. Additional information is requested within one month of receipt of this letter.

Responses may be submitted as specified in IE Bulletin 85-03, page 6, i.e.:

"The written reports shall be submitted to the appropriate Regional Administrator under oath or affirmation under provisions of Section 182a, Atomic Energy Act of 1954, as amended. Also, the original copy of the cover letters and a copy of the report shall be transmitted to the U.S. Nuclear Regulatory Commission Document Control Desk, Washington, DC 20555 for reproduction and distribution."

Questions addressing this issue may be forwarded to Richard J. Kiessel, IE (301) 492-8119.

Sincerely,

"Original Signed by C. E. Norelius"

Charles E. Norelius, Director Division of Reactor Projects

See Attached Distribution

RIII JAB Bauer/qg 7/31/86

Philips Philips 8608070082 860801

ADDCK 05000305

AM3/n Hehl RITI Norelius

103I O.

Distribution:

C. R. Steinhardt, Plant
Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
John J. Duffy, Chief
Boiler Section
Ness Flores, Chairperson
Wisconsin Public Service
Commission