D MB

AUG 0 1 1986

Docket No. 50-255

Consumers Power Company
ATTN: Dr. F. W. Buckman
Vice President
Nuclear Operations
212 West Michigan Avenue
Jackson, MI 49201

Gentlemen:

The preliminary review of the Palisades initial response to IE Bulletin 85-03 "Motor-Operated Valve Common Mode Failures During Plant Transients Due To Improper Switch Settings" indicates that it does not contain an adequate description of the program to assure valve operability as requested by Action Item e of the Bulletin. The program description in your response is little more than a paraphrase of the Bulletin's requirements. Additional information is requested within one month of receipt of this letter.

Responses may be submitted as specified in IE Bulletin 85-03, page 6, i.e.:

"The written reports shall be submitted to the appropriate Regional Administrator under oath or affirmation under provisions of Section 182a, Atomic Energy Act of 1954, as amended. Also, the original copy of the cover letters and a copy of the report shall be transmitted to the U.S. Nuclear Regulatory Commission Document Control Desk, Washington, DC 320555 for reproduction and distribution."

Questions addressing this issue may be forwarded to Richard J. Kiessel, IE (301) 492-8119.

Sincerely,

"Original Signed by C. E. Norelius"

Charles E. Norelius, Director Division of Reactor Projects

See Attached Distribution

RIII QAB Bluer/qg

7/31/86

VES

Phillips

RVII (n

RIII Norelius

8608070137 860801 PDR ADOCK 05000255 Q PDR

0 IE01

Distribution

Mr. Kenneth W. Berry, Director
Nuclear Licensing
J. F. Firlit, General Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
Nuclear Facilities and
Environmental Monitoring
Section