Consolidated Edison Company of New York, Inc. Indian Point Station Broadway & Bleakley Ave. Buchanan, NY 10511 Telephone (914) 737-8116

July 30, 1986

Re:

Indian Point Unit No. 2 Docket No. 50-247

Dr. Thomas E. Murley Regional Administrator - Region I U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

Dear Mr. Murley:

This letter is in response to IE Bulletin 86-02, "Static 'O' Ring Differential Pressure Switches." We have reviewed the differential pressure switches in use at Indian Point Unit No. 2. We have determined that there are no SOR Incorporated (formerly Static "O" Ring Pressure Switch Company) Series 102 or 103 differential pressure switches in safety related applications, and we do not plan to install them. Accordingly, these differential pressure switches are not listed in our Environmental Qualification Master Equipment List which is maintained in accordance with 10 CFR 50.49(b).

Should you or your staff have any questions, please contact us.

Very truly yours,

Murry Selman

Signed and sworn to before me this 30 day of July, 1986.

5/5 NOTEM PUBLIC NIV.S

WESTEHESTER COUNTY

60-481 1607

CUMMISSION EXPIRES NOV. 30, 1988

8608220303 840730 PDR ADDCK 05000247

CC: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 10555

Senior Resident Inspector U.S Nuclear Regulatory Commission P.O. Box 38 Buchanan, NY 10511

18.190.7.30.1