

APR 30 1986

Docket No. 50-440

Docket No. 50-441

The Cleveland Electric Illuminating
Company

ATTN: Mr. Murray R. Edelman

Vice President

Nuclear Group

Post Office Box 5000

Cleveland, OH 44101

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. Snell and others of this office on April 14-17, 1986, of activities at Perry Nuclear Power Plant, Units 1 and 2, authorized by NRC Facility Operating License No. NPF-45 and Construction Permit No. CPPR-149 and to the discussion of our findings with Mr. A. Kaplan and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection. However, weaknesses were identified which will need corrective action by your staff. These weaknesses are summarized in the attachment to this letter "Exercise Weaknesses." As required by 10 CFR Part 50, Appendix E, IV.F, any weaknesses that are identified must be corrected.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and any response to this letter will be placed in the NRC Public Document Room.

8605080122 860430
PDR ADOCK 05000440
G PDR

IED
11

The Cleveland Electric Illuminating Company 2

APR 30 1986

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

original signed by W.D. Shafer

W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosures:

- 1. Exercise Weaknesses
- 2. Inspection Reports
 - No. 50-440/86009(DRSS);
 - No. 50-441/86003(DRSS)

cc w/enclosures:

- J. J. Waldron, Manager, Perry
Plant Technical Department
- M. D. Lyster, Manager, Perry Plant
Operations Department
- L. O. Beck, General Supervising
Engineer, Nuclear Licensing and
Fuel Management Section
- DCS/RSB (RIDS)
Licensing Fee Management Branch
- Resident Inspector, RIII
- Harold W. Kohn, Ohio EPA
- Terry J. Lodge, Esq.
- James W. Harris, State of Ohio
- Robert H. Quillin, Ohio
Department of Health

RIII
JFK
Foster/kst
4/30/86
YES

RIII
Smith
Smith
4/30/86
YES

RIII
T/1/7
Sneff
YES

RIII
ack
Knop
yes

RIII
Shafer
Shafer

EXERCISE WEAKNESSES

1. The notification for the declaration of an Alert to the Coast Guard was not made during the required timeframe of 15 minutes. (50-440/86009-01; 50-441/86003-01) (Paragraph 5.a.2).
2. The inplant team responding to the simulated injured/contaminated man did not provide complete information to the Control Room regarding the accident site situation. (50-440/86009-02; 50-441/86003-02) (Paragraph 5.a.3).
3. Procedural criteria for downgrading an Emergency Action Level (EAL) to a lesser level were not considered in downgrading the Action Level, and an unapproved form was utilized in recovery planning. (50-440/86009-03; 50-441/86003-03) (Paragraph 5.b.1).