

## TELEPHONE REPORT

DATE 7/10/86 TIME 2115  
 FACILITY Nine Mile Point Unit 2 DOCKET NO. 50-410  
 LICENSEE'S OCCURRENCE IDENTIFICATION NO. (IF ANY) 86-16

BRIEF SUBJECT: Enclosing, orientation and location of Temperature  
Elements in Pipe Sleeves  
 DESCRIPTION OF OCCURRENCE, DEFICIENCY OR INCIDENT:

SE Pyco Temperature Elements have been enclosed in pipe sleeves that prevent air from directly impinging upon them. These elements are used to detect piping breaks. At the time of qualification the elements were exposed to the air. If left uncorrected the time needed to isolate blowdown could be prolonged. The additional blowdown could lead to pressures and temperatures that exceed the equipment qualification envelope. This condition could jeopardize the safe shutdown of the plant.

NOTIFICATION RECEIVED BY J. Linnell Jr.

RO:I Form 50  
 June 74

25- COLLINS  
 LINNELL  
 COOK  
 DURR  
 YOUNG  
 ✓ DOCKET RM

LIM 2  
 BV 2

~~1629~~  
 1627 0/1