

TELEPHONE REPORT

DATE 7/16/86 TIME 10:05 a.m.

FACILITY Seabrook I DOCKET NO. 50-443

LICENSEE'S OCCURRENCE IDENTIFICATION NO. (IF ANY) CDR 86-00-08

BRIEF SUBJECT: Cable Tray Holddown Spring Clips Not Torqued  
Per Vendor Requirements

DESCRIPTION OF OCCURENCE, DEFICIENCY OR INCIDENT:

Dave Maidrand, Assistant Project Manager, Licensing, NHY reported following information:

The cable tray torquing omission resulted from inconsistent interpretation of electrical notes and details resulting in improper translation of torque criteria into installation and inspection criteria.

Deficiency identified prior to completion of final torque verification program.

If uncorrected, this condition would invalidate the seismic analysis of cable tray support system.

Corrective action plan is being formulated and will be detailed in the applicant's written CDR, expected to sent promptly (by 7/18/86).

8608080337 860716  
PDR ADOCK 05000443  
S PDR

NOTIFICATION RECEIVED BY Don Haverkamp, Project Engineer, RPS 3C

RO:I Form 50  
June 74

CC:  
E. Wenzinger, DRP  
T. Elssner, DRP  
A. Carne, SRI, DRP  
CDR File - RE Docket Room ✓

~~FILED~~  
IE27 9/1