

APPENDIX A

NOTICE OF VIOLATION

Plateau Resources Limited
Shootaring Canyon Uranium
Processing Facility
Ticabon, Utah

Docket No.: 40-8698
License No.: SUA-1371

During an NRC inspection conducted February 24-26, 1987, one violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1987), the violation is listed below:

1. License Condition No. 11 requires, by reference to Appendix F of the renewal application, that specific calibration procedures be followed during routine instrument calibration.

Contrary to this requirement, two Eberline SAC 4 and two Eberline PRS-2 radiation detectors were not calibrated in accordance with procedures contained in Appendix F. Specifically, the necessary voltage plateau for the instruments was not determined during the period from February 1986 to February 1987.

This is a Severity Level IV Violation (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Plateau Resources Limited is hereby required to submit to this office, within 30 days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including for each violation:

- (1) the reason for the violation if admitted;
- (2) the corrective steps which have been taken and the results achieved;
- (3) the corrective steps which will be taken to avoid further violations; and
- (4) the date when full compliance will be achieved.

Where good cause is shown, consideration will be given to extending the response time.

-2-

Dated at NRC, Region IV, Uranium Recovery Field Office this 13th day of April, 1987.

151

Harry J. Pettengill, Chief
Licensing Branch 2
Uranium Recovery Field Office
Region IV