Docket No. 50-373 Docket No. 50-374

Commonwealth Edison Company ATTN: Mr. Cordell Reed Vice President Post Office Box 767 Chicago, IL 60690

Thank you for your letter dated July 3, 1986, informing us of the steps you have taken to correct the noncompliances which we brought to your attention in our letter dated June 6, 1986.

The actions you have taken appear to be appropriate; however, the following items were not addressed:

- 1. Has the training conducted in response to violations 373/86015-01A and 373/86015-01B been incorporated into the permanent operator training program? If not, when will this be accomplished?
- Was the summary of licensed operator responsibilities prepared by the NSO incorporated into the permanent operator training program? If not, how will this summary be made available to operators licensed in the future?
- 3. In light of the significant number of wrong unit errors at LaSalle since Unit 2 licensing, what effort did the Commonwealth Edison Company make to assure itself that this error was an isolated event and that there are no other improperly hung tags currently in the field?
- 4. How will the effectiveness of your corrective actions, especially those initiated to prevent wrong unit errors, be assessed?

Please respond to these questions within 20 days of the receipt of this letter.

Sincerely,

8607220452 860717 PDR ADOCK 05000373 PDR

Carl J. Paper ello, Director Division of Reactor Safety

See Attached Distribution

RIII

Hasse/mab

07/16/86

RIII

Phillips

RIII

Sw for Wright RIII

Hehl 8

RIII

Paperiello 1/17/86

1/1 FEO1

Distribution

cc: D. L. Farrar, Director
of Nuclear Licensing
G. J. Diederich, Plant
Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Phyllis Dunton, Attorney
General's Office,
Environmental Control
Division