## U.S. NUCLEAR REGULATORY COMMISSION

## REGION III

Report No. 50-346/87002(DRSS)

Docket No. 50-346

License No. NPF-3 Safeguards Group IV

Licensee: Toledo Edison Company

Edison Plaza 300 Madison Avenue Toledo, OH 43652

Facility Name: Davis-Besse Nuclear Power Station, Unit 1

Inspection At: Davis-Besse Site, Oak Harbor, Ohio

Inspection Conducted: January 5-9, 1987

Date of Last Physical Security Inspection: June 9 through July 15, 1986

Inspector: -

Bryan Drouin

Physical Security Inspector

1/28/87 Date

Approved By:

Safeguards Section

Inspection Summary

Inspection on January 5-9, 1987 (Report No. 50-346/87002(DRSS)) Areas Inspected: Included a review of Security Plan and Implementing Procedures; Management Effectiveness; Security Organization; Records and Reports; Physical Barriers - Protected Areas; Lighting; Assessment Aids; Access Control - Personnel; Detection Aids - Protected Areas and Previous Inspection Findings. Licensee action on IE Information Notices was also reviewed. The inspector familiarized himself with the licensee's Fitness For Duty Program.

Results: Eleven of twelve previous open items were closed as a result of this inspection. The licensee was found to in compliance with NRC requirements in eight of nine inspected areas during this inspection. The exception is noted

below:

Enclosure contains SAFEGUARDS INFORMATION Upon separation this page is Decontrolled

Assessment Aids: Some aspects of the camera coverage were inadequate.

The licensee has initiated several actions since the past inspection and completed certain security projects which have enhanced the overall effectiveness of the security program.

(Details: UNCLASSIFIED SAFEGUARDS INFORMATION)