
Alabama Power Company 600 North 18th Street Post Office Box 2641 Birmingham, Alabama 35291-0400 Telephone 205 250-1835

R. P. McDonald Senior Vice President 07 JAN 30 AIO: 25



the southern electric system

January 28, 1987

Docket Nos. 50-348 50-364

U. S. Nuclear Regulatory Commission Region II, Suite 2900 101 Marietta Street, N. W. Atlanta, Georgia 30323

Attention: Mr. David M. Verrelli

Gentlemen:

Joseph M. Farley Nuclear Plant NRC Inspection Report Nos. 50-348/86-28 and 50-364/86-28

In response to your letter of December 30, 1986, provided herein are planned corrective actions for the exercise weaknesses identified during the December Emergency Exercise.

Exercise weakness 50-348/86-28-02, 50-364/86-28-02: Failure to include in the initial protective action recommendation following declaration of the General Emergency the 22.5° sectors immediately adjacent to the principal zone exposed to the plume.

FNP will revise FNP-O-EIP-9, "Radiation Exposure Estimation and Classification of Emergencies", to provide additional guidance for evacuation and sheltering of the general public to ensure consideration is given to sectors adjacent to plume location when making protective action recommendations. This action will be completed by February 13, 1986.

Exercise weakness 50-348/86-28-03, 50-364/86-28-03: RMT 1 failed to implement the requirements of Procedure FNP-O-EIP-4 and demonstrated a lack of adequate training.

FNP will provide expanded RMT training to address specifically the weaknesses noted during the 1986 Emergency Exercise and to include field monitoring experience. The training is scheduled to be completed by July 1987.

If there are any questions, please advise.

Very truly yours,

R. P. McDonald

RPM: emb

8702100143 870128 PDR ADDCK 05000348 Q PDR IE-35