

ENCLOSURE 1

NOTICE OF DEVIATION

Georgia Power Company
E. I. Hatch Units 1 and 2

Docket Nos. 50-321 & 50-366
License Nos. DPR-57 & NPF-5

The following deviation was identified during an inspection conducted on February 10-13, 1986.

The licensee informed the NRC in its March 11, 1985 response to a Notice of Violation dated February 15, 1985, that the failure to complete the unmonitored release surveillances resulted from supervisors failing to utilize the Radiochemistry Department's Surveillance matrix to assure procedural compliance. Corrective actions included periodic information review of records by management to ensure continuing performance.

Contrary to the above, licensee management failed to take adequate corrective action to ensure continuing performance when the 1985 fourth quarter records pertaining to unmonitored release surveillance data were found missing.

Please provide, in writing within 30 days of the date of this Notice, a description of corrective actions regarding this deviation, actions taken to avoid further deviations, and the dates when these actions were or will be completed.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: MAR 20 1986

B604020691 B60320
PDR ADOCK 05000321
G PDR