

Report Period: May, 1997

UNIT SHUTDOWNS/REDUCTIONS  
(UNIT 1)

\*\*\*\*\*  
\* BYRON \*  
\*\*\*\*\*

| No. | Date    | Type | Hours | Reason | Method | LER Number | System | Component | Cause & Corrective Action to Prevent Recurrence                |
|-----|---------|------|-------|--------|--------|------------|--------|-----------|--|
| 3   | 5/03/97 | S    | 31:51 | B      | 9      | AP         |        |           | Took Turbine Off Line To Inspect Bus Ducts Due To Over Heating |
| 4   | 5/31/97 | F    | 9:38  | A      | 1      | MS         |        |           | Took Unit Off To Repair 1A MSIV                                |

\*\*\*\*\*  
\* Summary \*  
\*\*\*\*\*

| TYPE     | Reason                   | Method       | System & Component      |
|----------|--------------------------|--------------|-------------------------|
| F-Forced | A-Equip Failure          | F-Admin      | Exhibit F & H           |
| S-Sched  | B-Maint or Test          | G-Oper Error | Instructions for        |
|          | C-Refueling              | H-Other      | Preparation of          |
|          | D-Regulatory Restriction |              | Data Entry Sheet        |
|          | E-Operator Training      |              | Licensee Event Report   |
|          | & License Examination    |              | (LER) File (NUREG-0161) |

9708210134 970812  
PDR ADOCK 05000454  
R PDR