

Illmois Power Company Tel - 217 935-6220 Fax: 217-935-4632

Wayne D. Romberg

U-602817 2C.220

August 28, 1997

1/1 Iezz

Docket No. 50-461

10CFR50.73

Document Control Desk Nuclear Regulatory Commission Washington, D.C. 20555

Subject: Clinton Power Station - Unit 1

Licensee Event Report No. 97-002-01

Dear Madam or Sir:

Enclosed is Licensee Event Report (LER) No. 97-002-01: Failure to Complete Technical Specification 3.8.2 LCO Required Action B.4 Caused by Personnel Error. The enclosed report has been revised to identify the cause and corrective action for the event and provides a discussion of the safety significance on previous similar event information This report is being submitted in accordance with the requirements of 10CFR50.73.

This Licensee Event Report contains the following commitment:

 Revise CPS procedure 9080.01 to remove the requirement to bar over the Emergency Diesel Generator (EDG) when either the Division I or II EDG is inoperable.

Sincerely yours,

Wayne D. Romberg

Assistant Vice President

Wayno Ry

Enclosure

MRS/krk

040007

NRC Clinton Licensing Project Manager
NRC Resident Office, V-690
Regional Administrator, Region III, USNRC
Branch Chief, Region III, USNRC
Illinois Department of Nuclear Safety
INPO Records Center