Title: SALEM GENERATING STATION/HOPE CREEK GENERATING STATION: FAILURE TO MAKE A 10 CFR 73.71 NOTIFICATION BY THE STATION SECURITY DEPARTMENT

Licensee:

Public Service Electric & Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038

Docket Nos.: 50-272/311/354

Case No.: 1-96-024 Report Cate: July 25, 1997 Control Office: OI:RI Status: CLOSED

Reported by:

Reviewed and Approved by:

Tino.

Gerard F. Kenna, Special Agent Office of Investigations Field Office, Region I

Barry R. Letts, Director

Office of Investigations Field Office, Region I

WARNING

DO NOT DISSEMINATE, PLACE IN THE PUBLIC DOCUMENT ROOM OR DISCUSS THE CONTENTS OF THIS REPORT OF INVESTIGATION OUTSIDE NRC WITHOUT AUTHORITY OF THE APPROVING OFFICIAL OF THIS REPORT. UNAUTHORIZED DISCLOSURE MAY RESULT IN ADVERSE ADMINISTRATIVE ACTION AND/OR CRIMINAL PROSECUTION.

9710070198 971001 PDR ADOCK 05000272 G PDR Title:

SALEM GENERATING STATION/HOPE CREEK GENERATING STATION: FAILURE TO MAKE A 10 CFR 73.71 NOTIFICATION BY THE STATION SECURITY DEPARTMENT

Licensee:

Public Service Electric & Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038

Docket Nos.: 50.272/311/354

Case No.: 1.96-024 Report Date: July 25, 1997 Control Office: OI:RI Status: CLOSED

Reported by:

Reviewed and Approved by:

Gerard F. Kenna, Special Agent

Office of Investigations Field Office, Region I

CBarry R. Letts, Director Office of Investigations Field Office, Region I

WARNING

DO NOT DISSEMINATE, PLACE IN THE PUBLIC DOCUMENT ROOM OR DISCUSS THE CONTENTS OF THIS REPORT OF INVESTIGATION OUTSIDE NRC WITHOUT AUTHORITY OF THE APPROVING OFFICIAL OF THIS REPORT. UNAUTHORIZED DISCLOSURE MAY RESULT IN ADVERSE ADMINISTRATIVE ACTION AND/OR CRIMINAL PROSECUTION.

9710070198 971001 PDR ADOCK 05000272

.

SYNOPSIS

This investigation was initiated by the Nuclear Regulatory Commission (NRC). Office of Investigations (OI). Region I (RI). on June 28, 1996. to determine if Public Service Electric & Gas (PSEG) personnel and/or The Wackenhut Corporation (TWC) security personnel falsely documented that compensatory measures were in place within the required time. following the crash of the Salem Generating Station (SGS) security computer system on May 25, 1996.

Based on the evidence developed during this investigation. it was concluded that inaccurate information regarding the posting of compensatory measures was recorded in the Safeguards Evant Log. and that, at a minimum, the deliberate actions of two TWC personnel caused this documentation inaccuracy.