U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-346/87013(DRSS)

Docket No. 50-346

License No. NPF-3 Safeguards Group IV

Licensee: Toledo Edison Company

Edison Plaza

300 Madison Avenue Toledo, OH 42652

Facility Name: Davis-Besse Nuclear Power Station

Inspection At: Davis-Besse Site, Oak Harbor, Ohio

Inspection Conducted: June 1-4 on site; June 8-17 in the Region III Office

Date of Last Security Inspection: March 19 through April 13, 1987

Inspector:

Bryan Drouin

Security Inspector

Approved By:

6/30/87 Date

Inspection Summary

Inspection on June 1-17, 1987 (Report No. 50-346/87013(DRSS)) Areas Inspected: Management Effectiveness; Security Organization; Records and Reports; Testing and Maintenance; Physical Barriers - Protected Areas; Compensatory Measures; Assessment Aids; Access Control - Personnel and Fackages; Detection Aids - Protected Areas; Alarm Stations; Training and Qualification; Protection of Safeguards Information and Licensee action on previous inspection findings. We also reviewed two previously reported security events. We reviewed apparent discrepancies in security force members' statements concerning the an egedly inattentive shift supervisor event. Results: One of two previous inspection findings was closed. The licensee was in compliance with NRC requirements in 11 of 13 inspected areas. The exceptions are noted below.

Access Control - Personnel: Individuals were not properly escorted. Access to a Vital Area was not properly controlled.

Protection of Safeguards Information: Safeguards Information was not properly stored.

Two open items were identified during this inspection. One involved the testing of Protected Area alarms and the other involved alarm station reliability.

The apparent discrepancies in security officer statements were resolved to our satisfaction.

(Details: UNCLASSIFIED SAFEGUARDS INFORMATION)