10 CFR 2.201	SAFETY IN	SPECTION	
Jose R. Cumba Quiles, MD Aguas BueneasSt. Bldg. 12, Number 20 Santa Rosa, Bayomon, PR 00619		2. REGIONAL OFFICE U.S. Nuclear 101 Marietta Atlanta, 6A	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)		5. DATE OF INSPECTION
030-19053	52-19670-01		6/23/87
The inspection was an examination of the activities Regulatory Commission's (NRC) rules and regulation and representative records, interviews, with personn 1. Within the scope of this inspection, no violate 2. The inspector also verified the steps you have those actions at this time.	ns and the conditions of you nel, and observations by the itions were observed.  e taken to correct the violation	r license. The inspection on spector. The findings as one identified during the la	a result of this inspection are as follows:  ast inspection. We have no further questions on
THIS IS A NOTICE OF VIOLATION which			
A			was not p operly posted to indicate the presence
of a			. 10 CFR 20.203(b), (c), (d), (e) or 34.42.
C	0	License Condition Numb	were not properly maintained.
F. Reports or notifications ofwith 10 CFR	0	License Condition Numb	were not made in accordance
processory.			
I hereby state that within 30 days the actions described by the statement of corrective actions is made in according to the NRC.		of 10 CFA 2.201. No tur	