

08/31/87

PAGE 1

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO BECO

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	IR-87-01	IE BULLETIN	0		0	JOA	0788	THINNING OF PIPE WALLS IN NUCLEAR POWER PLANTS

RECEIVED
NRC
REGION V
1987 SEP 25 A 11:01

8710160021 870831
PDR ADOCK 05000312
P PDR

2/1
IE-51

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO BECO

PAGE 2

DOCKET	ITEM-NUH	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	86-07-10	INSP RPT (DEV)	0		0	HGA		CONTROL CABLE SHIELDING NOT PROTECTED AT UNGROUNDED END
		INSP RPT (DEV)	0	8706	0	ADD		FOLLOW IMPLEMENTATION DURING FUTURE INSPECTION
	87-11-01	INSP RPT (DEV)	E	8711	0	HPA		FAILURE TO MEET NOV RESPONSE COMMITMENT-CALIBRATION OF INSTRUMENTATION OUTSIDE CR
	87-14-02	INSP RPT (DEV)	0	8714	0	DJW		DEVIATION FOR USE OF RTU IN ESSENTIAL AIR FILTRATION SYSTEM

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO SECO

PAGE 3

DOCKET	ITEM-NO	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	83-34-03	INSP RPT (ENF)	R		0			FAILURE TO FOLLOW ABNORMAL TAG PROCEDURE
	86-07-01	INSP RPT (ENF)	R	8721	0	KFA		LICENSEE FAILED TO PROVIDE IMPLEMENT AND CONTROL CERTAIN REQUIRED EMERGENCY PROCEDURES
	86-14-02	INSP RPT (ENF)	P	8702	0	KMP		FAILURE TO MAINTAIN EP AND IMPLEMENTING PROCEDURES, REVIEW CORRECTIVE ACTION
	86-15-01	INSP RPT (ENF)	M		0	PGY		FAILURE TO ESTABLISH SURVEILLANCE PROCEDURES TO IMPLEMENT 10 CFR 50 APPENDIX I
	86-15-03	INSP RPT (ENF)	M		0	PGY		FAILURE TO REPORT IDENTIFIED AND MEASURED ISOTOPES IN EFFLUENTS AS REQUIRED BY T.S. 8.21
	86-15-05	INSP RPT (ENF)	M		0	PGY		FAILURE TO LIMIT LIQUID EFFLUENT DOSE TO LESS THAN 3 MREM PER YEAR T.S. 3.17.2
	86-15-09	INSP RPT (ENF)	M		0	PGY		FAILURE TO IMPLEMENT AND MAINTAIN LIQUID EFFLUENT PROCEDURES
	86-22-02	INSP RPT (ENF)	O	8636	0	ADD		FAIL TO STORE QUAL RECORD IN VAULT (REPEAT OF 803401) WSTR TRACKING I -DO NOT CLOSE TIL 803406 IS INSP
		INSP RPT (ENF)	O	8701	0	GYS		
		INSP RPT (ENF)	O	8711	0			
	86-37-02	INSP RPT (ENF)	M		0	MIC		FAILURE TO ESTABLISH PROCEDURES FOR MAINTENANCE AND CALIBRATION OF MONITORS R15701 & R15702

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO SECO

PAGE 8

DUCKET	ITEM#NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESLATIVE TITLE
50312	87-02-02	INSP RPT (ENF)	P		0	KHP		FOLLOW UP ON RESPONSE TO THE NOV REGARDING THE FAILURE TO CLASSIFY AN UNUSUAL EVENT
	87-03-02	INSP RPT (ENF)	O		0	ADD		PRZR SUPPORT UT INSP RESULTS
	87-03-04	INSP RPT (ENF)	E		0	ADD		FAILURE TO PROVIDE POSITIVE WELD IDENTIFICATION
	87-06-01	INSP RPT (ENF)	R		0	ADD		FAILURE TO ISSUE NCR FOR LKG PIPE
	87-06-02	INSP RPT (ENF)	R		0	ADD		FAILURE TO POST ABNORMAL TAG FOR REPAIR
	87-06-03	INSP RPT (ENF)	R		0	ADD		FAILURE TO PROVIDE IMMEDIATE NRC NOTIF FOR LER 85-13 & 85-20
	87-06-04	INSP RPT (ENF)	O		0	ADD		VOIDING OF NCR 86140
	87-06-05	INSP RPT (ENF)	R		0	ADD		QA MATL CONTROL REQMT
	87-06-06	INSP RPT (ENF)	R		0	ADD		IDENTIF OF SAFETY-RELATED MATL
	87-06-07	INSP RPT (ENF)	R		0	ADD		FAILURE TO PROVIDE 50.73 REPORT
	87-13-01	INSP RPT (ENF)	R		0	ADD		A REPLACEMENT FILTER FOR THE CBAST WAS ISSUED AND INSTALLED WITHOUT THE SMUD ACCEPT TAG

06/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO SECO

PAGE 5

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	87-13-02	INSP RPT (ENF)	R		0	ADD		CLEANLINESS PROCEDURE WAS NOT FOLLOWED FOR A CLASS 1 WORK REQUEST
	87-13-03	INSP RPT (ENF)	R		0	ADD		SPECIAL PROCESS, LPT, WAS NOT PERFORMED WITH A WORK CONTROLLING DOCUMENT
	87-14-01	INSP RPT (ENF)	0	8714	0	DJM		VIOLATION FOR FAILURE TO GENERATE AN NCR FOR BROKEN NCP CAPSCREWS
	87-16-01	INSP RPT (ENF)	R	8716	0	WPA		STROKE TESTING OF VALVES
	87-21-01	INSP RPT (ENF)	0	8721	0	WPA		FAILURE TO PERFORM CABLE ROUTING INSPECTIONS
	87-22-01	INSP RPT (ENF)	M		0	MIC		IMPLEMENTATION OF THE ALARA MANUAL

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
ENUD RANCHO BECO

PAGE 6

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	EN-87-19	INSP RPT (FOLLOWUP)	P		0	KMP		RESPONSE TO VIOLATION FOR FAILURE TO CORRECT DEFICIENCIES IN DRILLS AND EXERCISES
	83-16-02	INSP RPT (FOLLOWUP)	M		0			TESTING & CALIB OF BOTH MONITORING SYSTEMS AHU546A RADWASTE AREA VENT
		INSP RPT (FOLLOWUP)	M	8208	0			NRGM CALIBRATED, NRC MONITOR CALIB NOT EXAMINED-AAU546A NOT IN SERVICE
		INSP RPT (FOLLOWUP)	M	8528	0	MIC		
		INSP RPT (FOLLOWUP)	M	8611	0			TESTING & CALIB OF BOTH MONITORING SYSTEMS AHU546A RADWASTE AREA VENT
		INSP RPT (FOLLOWUP)	M	8627	0			
		INSP RPT (FOLLOWUP)	M	8637	0			
	83-16-12	INSP RPT (FOLLOWUP)	M	8611	0	MIC		RX BLDG VENT, NO HI RANGE MONITOR OR SAMPLING RPT PARA 118 5.
		INSP RPT (FOLLOWUP)	M	8722	0			
	84-01-02	INSP RPT (FOLLOWUP)	M	8611	0	MIC		NEW WASTE GAS SURGE TANK MONITOR- LOOK AT TYPE, RANGE & CALIBRATION
		INSP RPT (FOLLOWUP)	M	8637	0			

08/31/87

PAGE 7

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO BECO

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	84-11-03	INSP RPT (FOLLOWUP)	P	8535	0	KMP		INADEQUATE METEOROLOGICAL PROGRAM
		INSP RPT (FOLLOWUP)	P	8631	0			
	84-27-01	INSP RPT (FOLLOWUP)	M	8605	0	MIC		REEXAMINATION OF LOW-LEVEL RADIOACTIVE WASTE STORAGE BUILDING
		INSP RPT (FOLLOWUP)	M	8722	0			
	85-04-02	INSP RPT (FOLLOWUP)	R	8638	0	JOA		LICENSEE REVIEW AND VERIFICATION OF PAST COMMITMENTS AND DESIGN IMPLEMENTATION
	85-05-01	INSP RPT (FOLLOWUP)	P	8702	0	KMP		EVALUATE CHANGES IN SMUD MANAGEMENT
	85-14-01	INSP RPT (FOLLOWUP)	E		0	IJB	0486	ROCKBESTOS FIREWALL SR AND FIREWALL 3 CABLE
	85-14-02	INSP RPT (FOLLOWUP)	E		0	IJB	0486	IMPLEMENTATION OF EQ PROCEDURES
	85-26-02	INSP RPT (FOLLOWUP)	P	8710	0	KMP		INCLUDE OFFSITE IMPROVEMENT ITEMS (CONTRACT) SUPPORT IN CORRECTIVE ACTION LIST
	85-28-08	INSP RPT (FOLLOWUP)	M	8611	0	MIC		REPLACEMENT OF BROKEN CONTAINMENT BUILDING PURGE FLOW RATE MEASUREMENT DEVICE (RE-OPENED)
	85-28-11	INSP RPT (FOLLOWUP)	M	8611	0	MIC		INSTALLATION OF PERM R15017A AND R15017B, REVIEW OF

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO BECO

PAGE 8

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
56312	85-28-11	INSP RPT (FOLLOWUP)	M	8637	0			
	86-02-KP	INSP RPT (FOLLOWUP)	P	8710	0	KMP		PROVIDE E PLAN FIRST AID TRAINING
	86-06-02	INSP RPT (FOLLOWUP)	P	8702	0	KMP		REVIEW STEPS TAKEN TO IMPROVE NOTIFICATION OF PLANT STAFF TO T SAFETY PRECAUTIONS
	86-07-03	INSP RPT (FOLLOWUP)	0		0	HGA		IDADS INDICATED ERRONEOUS FLOWS FO EMERG CR HVAC SYSTEM
	86-13-02	INSP RPT (FOLLOWUP)	R		0	GPP		LACK OF PROPER CORRECTIVE ACTIONS WHEN IDENTIFIED VALVES NOT ON PA
	86-14-03	INSP RPT (FOLLOWUP)	P	8710	0	KMP		REVIEW CORRECTIVE ACTION ON ITEMS IDENTIFIED DURING LICENSEE'S 50. AUDIT
	86-15-08	INSP RPT (FOLLOWUP)	M		0	PGY		VERIFY THAT THE LICENSEE UPDATES THE FEAR TO CORRECT LIQUID EFFLU PRACTICES
	86-15-11	INSP RPT (FOLLOWUP)	M		0	PGY		FOLLOW UP TO DETERMINE IF THE LICENSEE INTENDS TO CORRECT T.S. 6.9.2.3.1
	86-15-12	INSP RPT (FOLLOWUP)	M		0	PGY		VERIFY CORRECTED SEMIANNUAL EFFLUENT RELEASE REPORTS
	86-15-13	INSP RPT (FOLLOWUP)	M		0	PGY		ESTABLISH VALIDITY OF ODCM REVISIO TO CHANGE BIOACCUMULATION FACTOR FOR CESIUM
	86-17-02	INSP RPT (FOLLOWUP)	R	8622	0	AOH	0986	ESTABLISH A FORMAL PROGRAM TO CALIBRATE SAFETY-RELATED INSTRUMENTS NOT ADDRESSED BY T.S.

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO BECO

PAGE 9

DOCKET	ITEM#NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	86-17-02	INSP RPT (FOLLOWUP)	R	8711	0	WPA		
	86-18-07	INSP RPT (FOLLOWUP)	E	8706	0	ADD		WATER CONTROL IN THE TSC ON FIRE SYSTEM ACTUATION; PENDING COMPLETION OF LICENSE ACTION
		INSP RPT (FOLLOWUP)	E	8711	0	WPA		
		INSP RPT (FOLLOWUP)	E	8715	0	COR		LACK OF DRAINAGE CAPABILITY F/FIRE SUPPRESSION WATER IN THE TSC
	86-25-01	INSP RPT (FOLLOWUP)	E		0	WJM		CLARIFICATION OF QA/QC PROCEDURES ADDRESSING SAR QAP DESCRIPTION
	86-30-01	INSP RPT (FOLLOWUP)	R		0	CYM		MAINTENANCE TROUBLESHOOTING PROGRAM TO BE ESTABLISHED PRIOR TO RESTART
	86-32-03	INSP RPT (FOLLOWUP)	P	8710	0	KMP	1010	USING TSC AREA TO BRIEF MAINTENANCE TEAMS DURING EXERCISE
	86-32-04	INSP RPT (FOLLOWUP)	P		0	GGB	1010	INADEQUATE RADIOLOGICAL CONTROL DEMONSTRATED DURING EXERCISE
	86-32-05	INSP RPT (FOLLOWUP)	P		0	GGB	1010	INADEQUATE ASSEMBLY/ACCOUNTABILITY DURING EXERCISE
	86-32-06	INSP RPT (FOLLOWUP)	P		0	GGB	1010	INADEQUATE TRAINING OF DOSE ASSESSMENT PERSONNEL DEMONSTRATED DURING EXERCISE
	86-37-01	INSP RPT (FOLLOWUP)	M	8705	0	MIC		VERIFY COMPLIANCE WITH TECHNICAL SPECIFICATIONS, SECTION 6.18 PRIOR TO RETURNING THE UNIT TO FULL PWR

06/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SHUD RANCHO BECO

PAGE 10

DOCKET	ITEM-NO	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	86-37-03	INSP RPT (FOLLOWUP)	H	8721	0	HPA		REVIEW LICENSEE EVAL ASSOCIATED W/ THE LOCATIONS THAT MONITORS R1570 & R15702 WERE INSTALLED
		INSP RPT (FOLLOWUP)	H	8721	0			
	86-41-01	INSP RPT (FOLLOWUP)	H		0	HPA		AFW PMP TURN OS TRIP SETPT
	86-41-02	INSP RPT (FOLLOWUP)	H		0	HPA		POT AFW FCO INDUCED SG TUBE VIBR
	86-41-03	INSP RPT (FOLLOWUP)	H		0	HPA		AFW FULL FLO TEST LINE
	86-41-04	INSP RPT (FOLLOWUP)	H		0	HPA		EFFECTS OF AFW PUMP RUNOUT OPS
	86-41-05	INSP RPT (FOLLOWUP)	H		0	HPA		ERRORS IN AFW PUMP PERFORMANCE CALCS
	86-41-07	INSP RPT (FOLLOWUP)	H		0	HPA		AFW PROB NOT SCHED FOR RESOL PRIOR TO RESTART
	86-41-08	INSP RPT (FOLLOWUP)	H		0	HPA		EFIC EXCESS FLO CHK VLV EQ QUALS
	86-41-10	INSP RPT (FOLLOWUP)	H		0	HPA		PROVISIONS TO TEST EFIC MAINT BYPASS
	86-41-11	INSP RPT (FOLLOWUP)	H		0	HPA		125VDC PROB CORR ACTION

88/31/87

PAGE 11

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
BMUD RANCHO BECO

DOCKET	ITEM-NO	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	86-41-12	INSP RPT (FOLLOWUP)	H		0	WPA		125VAC VITAL - PROB CORR ACTION
	86-41-13	INSP RPT (FOLLOWUP)	H		0	WPA		480VAC PROB CORR ACTION
	86-41-14	INSP RPT (FOLLOWUP)	H		0	WPA		4160VAC PROB CORR ACTION
	86-41-18	INSP RPT (FOLLOWUP)	H		0	WPA		ONE LINE DIAG E101 CORRECTION
	86-41-22	INSP RPT (FOLLOWUP)	H		0	WPA		THERMAL OVERLOAD PROT/ALARMS FOR MVS
	86-41-23	INSP RPT (FOLLOWUP)	H		0	WPA		REVIEW OF GCIS DRAFT
	86-41-29	INSP RPT (FOLLOWUP)	H		0	WPA		DIFF STRK TIME ACC CRIT - FV20527 & FV20528
	86-41-33	INSP RPT (FOLLOWUP)	H		0	WPA		ADEQ OF PLT OF PROCB
	86-41-34	INSP RPT (FOLLOWUP)	H		0	WPA		AFM PUMP RUNOUT INDIC PROC/TRNG
	86-41-35	INSP RPT (FOLLOWUP)	H		0	WPA		OP TRNG CONCERNS
	86-41-37	INSP RPT (FOLLOWUP)	H		0	WPA		IMPLEMENTATION OF PH TREND ANALYSIS PROC

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO SECO

PAGE 12

DOCKET	ITEM-NO	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	86-41-38	INSP RPT (FOLLOWUP)	H		0	WPA		QA AUDIT PRG DEFICIENCIES
	86-41-39	INSP RPT (FOLLOWUP)	H		0	WPA		QA SURVEILLANCE PRG ISSUES
	86-41-40	INSP RPT (FOLLOWUP)	H		0	WPA		EFFECTIVENESS OF QA CORRECTIVE ACTION PRG
	86-41-41	INSP RPT (FOLLOWUP)	H		0	WPA		OPEN LRS REPORT RECOMMENDATIONS
	86-41-42	INSP RPT (FOLLOWUP)	H		0	WPA		REVALIDATE ADEQ OF QCI-12 REVIEWS
	86-41-43	INSP RPT (FOLLOWUP)	H		0	WPA		CONTROL OF 88R REV 1 DOCS
	86-41-44	INSP RPT (FOLLOWUP)	H		0	WPA		SMUD NUC ORG FOR RESTART
	87-02-01	INSP RPT (FOLLOWUP)	P		0	KMP		REVIEW IMPROVEMENTS TO ITEMS IDENTIFIED IN PARAGRAPH 4 OF REC 50-312/87-02
	87-04-01	INSP RPT (FOLLOWUP)	O		0	DJM		RESOLVE SPLICES WHICH WERE NOT PROPERLY INSTALLED AND CORRECTIVE TO EQ FILE
	87-04-03	INSP RPT (FOLLOWUP)	O		0	DJM		FOLLOW UP ITEMS OF CONCERN TO SEE IF ACCEPTABLE
	87-05-01	INSP RPT (FOLLOWUP)	H		0	MIC		REVIEW ACTIONS TAKEN BY LICENSEE RESOLVE INTERNAL AUDIT FINDINGS

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
BMUD RANCHO SECO

PAGE 13

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	87-05-04	INSP RPT (FOLLOWUP)	M		0	MIC		FAILURE TO PROVIDE 10 CFR 71.105(D) & 49 CFR 173.1(B) & IE BULLETIN 79-19 TRAINING QAP 17 CONCERNS
	87-06-09	INSP RPT (FOLLOWUP)	0		0	ADD		
	87-07-01	INSP RPT (FOLLOWUP)	S	8707	0	DZB	0388	SAFETY CONCERN ASSOC W/PUSH- BUTTON SWITCH ADJACENT TO VITAL DOORS
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-02	INSP RPT (FOLLOWUP)	S	8707	0	DZB	0388	POSTING OF AREA LOCATION OR VA NUMBER INSIDE VA NEAR TELEPHONE
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-03	INSP RPT (FOLLOWUP)	S	8707	0	DZB	0388	INSTALL TELEPHONES INSIDE ALL VA DOORS
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-04	INSP RPT (FOLLOWUP)	S	8707	0	DZB	0388	SECURITY AUDITOR TO COMPLETE TRAINING
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-05	INSP RPT (FOLLOWUP)	S	8707	0	DZB	0388	RELOCATE SECURITY ANTENNA

08/31/87

REGION 3
 OUTSTANDING ITEMS REPORT
 ALL OPEN ITEMS (SORTED BY TYPE)
 SMUD RANCHO SECO

PAGE 14

DUCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	87-07-05	INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-06	INSP RPT (FOLLOWUP)	S	8707	0	DZS	0388	COMPLETE WORK ORDERS F/SECURITY AT DIESEL GENERATOR BLDG
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-07	INSP RPT (FOLLOWUP)	S	8707	0	DZS	0388	VERIFY COMPLETION OF WORK ORDERS F/SITE LIGHTING TO INCLUDE IMPROVE LIGHTING IN ALL IDENT. AREAS
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-09	INSP RPT (FOLLOWUP)	S	8707	0	DZS	0388	VERIFY INSTALLATION GE STEEL UNISTRUTS
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-10	INSP RPT (FOLLOWUP)	S	8707	0	DZS	0388	INSTALL ALARM SYSTEM ON TANK FARM FENCE
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-12	INSP RPT (FOLLOWUP)	S	8707	0	DZS	0388	VERIFY REMOVAL OF EXTRA LOCKING BOLT ON STATIONARY SIDE OF VA DOUBLE DOORS
		INSP RPT (FOLLOWUP)	S	8718	0			

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO BECO

PAGE 15

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	87-07-13	INSP RPT (FOLLOWUP)	S	8707	0	DZS	0388	VERIFY IMPROVEMENT TO ALARM STATIONS
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-14	INSP RPT (FOLLOWUP)	S	8707	0	UZH	0388	REMOVE EXPOSED WIRING IN VEH SEARCH AREA
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-15	INSP RPT (FOLLOWUP)	S	8707	0	DZS	0388	VERIFY DATA RETRIEVAL P/ALARM STATION COMPUTERS
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-16	INSP RPT (FOLLOWUP)	S	8707	0	DZS	0388	VERIFY INSTALLATION OF SWITCH IN CAS TO OPERATE MAIN GATE DURING EMERGENCIES
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-17	INSP RPT (FOLLOWUP)	S	8707	0	DZS	0388	VERIFY INSTALLATION OF REMAINING LOCALIZED INTELL. UNITS IN VA DOORS
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-18	INSP RPT (FOLLOWUP)	S	8707	0	DZS	0388	VERIFY OPERATION OF CARD KEY DETECTOR

88/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO BECO

PAGE 16

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	87-07-18	INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-19	INSP RPT (FOLLOWUP)	S	8707	0	DZS	0388	VERIFY INSTALLATION OF INTRUSION ALARM TO OUTER PERIMETER FENCE
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-07-20	INSP RPT (FOLLOWUP)	S	8707	0	DZS	0388	VERIFY INSTALLATION OF STROBE LIGHT ON OUTER FENCE
		INSP RPT (FOLLOWUP)	S	8718	0			
	87-13-04	INSP RPT (FOLLOWUP)	R		0	WPA		REPORTABILITY PER PART 21 OF RM-80 PRINTED CIRCUIT BOARD LER85-15-L
	87-18-01	INSP RPT (FOLLOWUP)	S		0	DZS		INSTALL PROTECTIVE COVERS OVER TOGGLE SWITCHES
	87-18-02	INSP RPT (FOLLOWUP)	S		0	DZS		LICENSEE EVALUATION OF COMPONENTS OF VITAL EQUIPMENT
	87-18-03	INSP RPT (FOLLOWUP)	S		0	DZS		LICENSEE TO ADDRESS ISSUES CONCERNING MONTHLY REVALIDATION OF VA ACCESS AUTHORIZATION
	87-19-01	INSP RPT (FOLLOWUP)	P		0	KMP		EXAMINE RESPONSE TO 50,54(T) AUDIT FOR 1987 TO DETERMINE EFFECTIVNE OF PROGRAM TO ADDRESS CONCERNS
	87-22-02	INSP RPT (FOLLOWUP)	M		0	MIC		REVIEW OBSERVATIONS ASSOCIATED WITH 1986 ENVIRONMENTAL REPORT, PARAGRAPH 9

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO SECO

PAGE 17

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	87-22-03	INSP RPT (FOLLOWUP)	M		0	MIC		EXAMINE LICENSEE'S EVALUATION RELATED WITH THE VENDOR SUPPLIED TLD ANOMALIES
	87-22-04	INSP RPT (FOLLOWUP)	M		0	MIC		EXAMINE LICENSEE'S EVALUATION OF THEIR PANASONIC TLD SYSTEM TO ACCURATELY MEASURE BETA RADIATION

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
BMUD RANCHO SECO

DOCKET	ITEM#NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	GL-85-06	GENERIC LETTER	E		0	KDI	0386	QA GUIDANCE FOR ATWS EQUIP THAT IS NOT SAFETY-RELATED
	GL-85-22	GENERIC LETTER	0		0	TAY		POTENTIAL FOR LOSS OF POST-LOCA RECIRC CAP DUE TO INSULATION OEBRI BLOCKAGE
	GL-86-05	GENERIC LETTER	E	8721	0	WPA	0886	FOLLOWUP TO GL83-10ERF. IMPLEMENTATION OF TMI ITEM II.K.3. "AUTO TRIP OF RCP8"

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO BECO

PAGE 19

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	IN-85-71	INFO NOTICE	E	8601	0	CBC	1186	CILRT
	IN-85-80	INFO NOTICE	P		0	RIF		TIMELY EMERGENCY CLASSIFICATION AND NOTIFICATION
	IN-86-03	INFO NOTICE	R	8630	0	CYM		EG WIRING IN LIMITORQUE MOTOR VALVE OPERATOR
	IN-86-90	INFO NOTICE	M		0	PGY	1187	REQUESTS TO DISPOSE OF VERY LOW-LEVEL RADIOACTIVE WASTE PURSUANT TO 10 CFR 20.302
	IN-86-98	INFO NOTICE	P		0	RIF		OFFSITE MEDICAL SERVICES
	IN-87-08	INFO NOTICE	O		0	JOA	1287	DEGRADED MOTOR LEADS IN LIMITORQUE DC MOTOR OPERATORS
	IN-87-31	INFO NOTICE	M		0	PGY		IN-87-31 BLOCKING BRACING AND SECURING OF RADIOACTIVE MATERIAL PACKAGES IN TRANSPORTATION
	IN-87-32	INFO NOTICE	N		0	PGY		INFO NOTICE NO. 87-32 DEFICIENCIES IN THE TESTING OF NUCLEAR GRADE ACTIVATED CHARCOAL
	IN-87-39	INFO NOTICE	M		0	PGY		IN-87-39 CONTROL OF HOT PARTICLE CONTAMINATION AT NUCLEAR POWER PLANT

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO SECO

PAGE 20

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	R-87-10	OTHER	E	8715	0	COR		RCS HIGH POINT VENT VALVES SPURIOUS ACTUATION
	R-87-12	OTHER	E	8715	0	COR		FAILURE TO PERFORM SURVEILLANCE PROCEDURES
	R-87-13	OTHER	E	8715	0	COR		REDUNDANT INSTRUMENT CABLES LOCATED IN SAME FIRE AREA
	R-87-15	OTHER	E	8715	0	COR		CO2 PROTECTED ZONES LEFT DEACTIVATED
	8-A3-01	OTHER	E	8715	0	COR		RCP ROOM FIRE DETECTORS NOT TESTED
	8-87-04	OTHER	E	8715	0	COR		BREACHED FIRE BARRIERS
	04-27-87	OTHER	B	8718	0	DZB		CUTTING OF TWO WIRES
	86-01-KP	OTHER	P		0	GQB		IMPROVE OOSE ASSESSMENT CAPABILITIES
	87-01-	OTHER	E		0	AFC		NUMEROUS BREACHED FIRE BARRIERS TO BE REPAIRED PRIOR TO RESTART
		OTHER	E	8706	0	AFC		UPDATE OF PREVIOUS REPORTS REMAINS OPEN PENDING FURTHER LICENSEE ACTION
	87-07-80	OTHER	M		0	MIC		REVIEW ODR ASSOCIATED WITH THE DRAINING OF NSRW (RAW WATERS)

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SAND RANCHO SECO

PAGE 21

DOCKET	ITEM#NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	TI-00-20	TEMP INSTR (TI)	0		0	JOA	0288	INSPECTION TO DETERMINE COMPLIANCE WITH ATMS RULE 10 CFR 50.62
	TI-00-22	TEMP INSTR (TI)	M		0	HIC		TEMPORARY IE INSTRUCTION 2500/221 COLLECTION OF COLLOCATED TLO MEASUREMENT RESULTS
	TI-15-65	TEMP INSTR (TI)	0		0	JOA		TMI ACTION PLAN REQUIREMENT FOLLOWUP
	TI-15-71	TEMP INSTR (TI)	0		0	TAY		IER 82-02 THREADED FASTENERS IN RCPs OF PWRs
	TI-15-73	TEMP INSTR (TI)	0		0	TAY		IER-85-03 MOV COMMON MODE FAILURES DURING PLANT TRANSIENTS DUE TO IMPROPER SWITCH SETTINGS
		TEMP INSTR (TI)	0	R636	0	ADD		MASTER TRACKING ITEM - DO NOT CLOSE UNTIL LER 83-37-L1 HAS BEEN INSPECTED
	TI-15-75	TEMP INSTR (TI)	0		0	TAY		INSPECTION OF LIMITORQUE MVO WIRING FOR EQ-50.49
	TI-15-78	TEMP INSTR (TI)	E		0	JOA	0188	INSPECTION OF QUALITY VERIFICATION FUNCTIONS
	TI-15-79	TEMP INSTR (TI)	R		0	TAY		EMERGENCY OPERATING PROCEDURES
	TI-15-84	TEMP INSTR (TI)	0		0	JOA	0388	VERIFICATION OF COMPLIANCE W/ORDER CONCERNING PRIMARY COOLANT SYSTEM VENT VALVES
	TI-15-86	TEMP INSTR (TI)	0		0	JOA	0388	INSPECTION OF LICENSEE'S ACTIONS TO IMPLEMENT 2L81-21, NATURAL CIRCULATION COOLDOWN

08/31/87

REGION 9
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SHUD RANCHO BECO

PAGE 22

DOCKET	ITEM#	NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	TI-15-87		TEMP INSTR (TI)	0		0	JOA	0388	INSP TO VERIFY LICENSEE'S POST- ACCIDENT INSTRUMENTATION SYSTEMS INSTALLED & MEET REG GD 1.97
	TI-15-88		TEMP INSTR (TI)	0		0	JOA	0488	INSPECTION OF ACTIONS TAKEN TO IMPLEMENT GUIDELINES FOR FLOOD PROTECTION OF EQUIPMENT
	TI-15-91		TEMP INSTR (TI)	0		0	JOA	0388	INSPECTION TO VERIFY IF RTB MODIFICATIONS HAVE BEEN IMPLEMENTED

08/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO SECO

PAGE 23

SOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	85-08-02	INSP RPT (UNR)	R		0	JHE		BATTERY SURVEILLANCE TEST (DISCHARGE TEST) NOT IN ACCORDANCE WITH TECH SPEC
	85-25-02	INSP RPT (UNR)	R	8530	0	Jhr		NCR NOT ISSUED ON BROKEN CAPSCREWS FOR THE RCP
		INSP RPT (UNR)	R	8621	0	CYM		
	85-31-01	INSP RPT (UNR)	R		0	CYM		USAR UPDATE REQUIRED TO IDENTIFY CROSSCONNECTED HPI ALIGNMENT - AL SEE POL 85-27-03
		INSP RPT (UNR)	R	8636	0	ADD		MASTER TRACKING ITEM; DO NOT CLOSE UNTIL P-85-27-03 HAS BEEN INSPECT
		INSP RPT (UNR)	R	8711	0	WPA		
		INSP RPT (UNR)	R	8721	0	WPA		
	86-03-03	INSP RPT (UNR)	0	8636	0	ADD		BATT SURV PROG; MASTER TRACKING ITEM-00 NOT CLOSE TIL FOLLOWING ITEMS INSPECT R-8603-0, 8607-12THRU-17, 8608-03& DISCREPANCIES WITH LICENSEE'S PIPING CLASSIFICATION VS SER.
	86-18-05	INSP RPT (UNR)	R	8709	0	ADD		
	86-18-06	INSP RPT (UNR)	R	8709	0	ADD		CURRENT PIPING CLASSIFICATION DOES NOT IDENTIFY SEISMIC PIPING P-00 THE CLASS I BOUNDARY INST AIR SVS MODS
	86-41-06	INSP RPT (UNR)	H		0	WPA		

08/31/87

REGION 3
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO BECO

PAGE 24

DOCKET	ITEM#NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	86-41-09	INSP RPT (UNR)	H		0	WPA		EFIC SYS 10CPR50.50 ANALYSIS
	86-41-15	INSP RPT (UNR)	H		0	WPA		CBT OVERPRZR & UNDERPRZ PROT
	86-41-16	INSP RPT (UNR)	H		0	WPA		DC CIRCUIT BRKR SIZING CALC
	86-41-17	INSP RPT (UNR)	H		0	WPA		BATT SIZING CALC
	86-41-19	INSP RPT (UNR)	H		0	WPA		AC CIRC BRKR SIZING CALC
	86-41-20	INSP RPT (UNR)	H		0	WPA		UNDERRATED DC CABLES
	86-41-21	INSP RPT (UNR)	H		0	WPA		IDADS COMPTX ALARM MODS
	86-41-24	INSP RPT (UNR)	H		0	WPA		PLT DWG CONTROL
	86-41-25	INSP RPT (UNR)	H		0	WPA		DESIGN CALCS
	86-41-26	INSP RPT (UNR)	H		0	WPA		IST PROG APPROVAL
	86-41-27	INSP RPT (UNR)	H		0	WPA		SURV & IST DATA TRENDING

06/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SHUD RANCHO BECO

PAGE 25

DOCKET	ITEM-NUH	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	86-41-28	INSP RPT (UNR)	H		0	WPA		AFW PUMP CAP TEST
	86-41-30	INSP RPT (UNR)	H		0	WPA		AFW SURV TEST PROCS
	86-41-31	INSP RPT (UNR)	H		0	WPA		DC SYS SURV TESTING
	86-41-32	INSP RPT (UNR)	H		0	WPA		ADMIN CONTROL OF PLT SYS
	86-41-36	INSP RPT (UNR)	H		0	WPA		CORRECTIVE MAINT PROCS
	87-03-01	INSP RPT (UNR)	E		0	ADD		QA ISI SURVEILLANCE EFFECTIVENESS
	87-03-03	INSP RPT (UNR)	E		0	ADD		UT REPORT DOCUMENTATION INADEQUATE
	87-04-02	INSP RPT (UNR)	0		0	DJM		RESOLVE IF INSTALLATION OF SPLICE WITHOUT CEMENT IS ACCEPTABLE
	87-06-08	INSP RPT (UNR)	0		0	ADD		50.39 REVIEW FOR CABLE TRAY OVERFILL/MIXING
	87-21-02	INSP RPT (UNR)	0	8721	0	WPA		ACCURACY OF CABLE AMPACITY CALC

06/31/87

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
SMUD RANCHO BECO

PAGE 26

DOCKET	ITEM-NO	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	EMPLOYEE INITIALS	ACTION DATE	DESCRIPTIVE TITLE
50312	87-15-01	50.55E RPT	E		0	COR		50.55(E)-CO2 & FIRE DETECTION ALARM SYSTEM DESIGN
	87-15-02	50.55E RPT	E		0	COR		50.55(E)-FIRE PUMP OPERABILITY
	87-15-03	50.55E RPT	E		0	COR		50.55(E)-ORGANIZATION & STAFFING F/FIRE PROT PROG IMPLEMENTATION
	87-15-04	50.55E RPT	E		0	COR		50.55(E)-SYSTEM REVIEW PACKAGE LICENSEE IDENTIFIED FIRE PROT PROGRAM DEFICIENCIES

08/31/87

REGION 5
LICENSEE EVENT REPORT

PAGE 1

DUCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	NAME	ACTION DATE	DESCRIPTIVE TITLE
50312	85-02-P	PART 21	0		0	CYM		PART 21: ANACON CL-2 MONITORS
	85-13-P	PART 21	E		0	ADD		PT 21-TDI ENGINE GEN CONTROL PANEL; MSTR TRACKING ITEM FOR 8508P, 8521P, 8522P, 8601P, 8604P, 8608P, 8610P, 8616P WILL NOT BE CLOSED UNTIL THE OTHER ITEMS HAVE BEEN INSPECTED-OTHER ITEMS HAVE BEEN ADMINISTRATIVELY CLOSED
		PART 21	E	8636	0			PART 21: LIMITORQUE VALVE ACTUATORS
	85-14-P	PART 21	0		0	TAY		
	85-23-P	PART 21	0		0	TAY		PART 21: ROSEMOUNT PERF SPEC REPORT DOES NOT ADDRESS ZERO SHIFT DUE TO PROCESS PRESS
	86-14-P1	PART 21	0		0	GYS		PART 21 - AUTOMATIC SPRINKLER CORP MERCURY CHECK DEVICE LEAKAGE AND UPDATE ON MODEL C VALVES
	86-20-P	PART 21	R		0	MPR		PART 21 EOL SUSCEPTIBILITY OF ESH LINE INSTR, BY FOXBORO, TO DEGRADE OR DETERIORATE CAUSING FAILURE
	86-23-P	PART 21	R		0	MPR		PART 21-STATIONARY SLEEVE ON THRUST BRG OF ATWOOD & MORRILL HSIV MUST BE MACHINED TO PREVENT GALLING
	86-26-P	PART 21	R		0	MPR		P21-CHG IN ALLOW OPER REPEATABILITY RANGES OF 80R INC 9, 861 PREFIXD GAU PRESS 8W. 12 TO 5X LOG 8M118
	86-28-P	PART 21	0		0	MPR		PART 21: USE OF CONTROMATICS MANUAL JACKSCREW FOR REG. CYCLING NOT ACCEPTABLE, IF USED MODS TO BE MADE
	87-02-P	PART 21	0		0	GYS		PART 21 - GE RELAYS USED BY DELTA CONTROLS FOR TRANSAMERICA DELAVAL DIESEL GENERATORS
	87-03-P	PART 21	0		0	GYS		PART 21 - HBC BROWN BOVERI ITC 278 BATTERY GROUND DETECTOR RELAY

08/31/87

REGION 5
 LICENSEE EVENT REPORT

PAGE 2

SOCKET	ITEM#NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	NAME	ACTION DATE	DESCRIPTIVE TITLE
50312	87-03-P1	PART 21	N		0	MIC		10 CFR 21.21 NOTIFICATION OF A DESIGN REVISION TO MUPAC MODEL N-55 PACKAGE
	87-08-P	PART 21	0		0	CSC		PT 21-GE WFA RELAY-ARMATURE BINDING W/DE-ENERGIZED, RESULTED IN FAILED CONTACT OPERATION
	87-09-P	PART 21	0		0	CSC		PT 21-SQUARE D COMPANY/GM DIESEL GENRL PUMP RELAY, CLASS 850, TYPE KPD-13, 130 VDC-FAILED TO OPEN
	87-11-P	PART 21	E	8721	0	WPA		PT 21 INACCURATE NPSH CURVE F/R&W (CANADA) MOD K8MK(10X12X21) PUMP F/MIDLAND-INTENDED USE FOR DHR PUMP
	87-12-P	PART 21	E	8721	0	WPA		IMO DELAYAL-STATIC EXCITER VOLTAGE REGULATOR MAY NOT RESET ON DSR & DSHV STANDBY DIESEL GENERATOR
	87-14-P	PART 21	R		0	CSC		IMO DELAYAL INC POTENTIAL DEFECT IN COMPONENT STANDBY DIESEL GEN. RE AIR PRESSURE REGULATOR

08/31/87

REGION 3
LICENSEE EVENT REPORT

PAGE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	NAME	ACTION DATE	DESCRIPTIVE TITLE
90312	86-20-Y0	REPORT (OTHER)	M		0	MIC		INCONSISTENCY WITH CORE DAMAGE ASSESSMENTS USING METHODS DEVELOPED BY STONE & WEBSTER (SPECIAL REPORT)

08/31/87

REGION 5
LICENSEE EVENT REPORT

PAGE 4

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	NAME	ACTION DATE	DESCRIPTIVE TITLE
50312	80-26-10	REPORTABLE OCCU	R		0		0683	SUBCOOLING REQUIREMENT RESULTS IN GREATER OFFSITE DOSE FOR OTSG LEAK
		REPORTABLE OCCU	R	8121	0		0683	PEND ATOG GUIDELINES AND REVISE FBAR

08/31/87

REGION 5
LICENSEE EVENT REPORT

PAGE 5

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	NAME	ACTION DATE	DESCRIPTIVE TITLE
50312	85-01-L3	REPORTABLE OCCU	R		0	WPA		LOSS OF CTMT INTEG VIA PASS VLVS
	85-16-L2	REPORTABLE OCCU	R		0	WPA		SPURIOUS CLOSURE=DHR DROP LINE ISOLATION VALVE
		REPORTABLE OCCU	R	8721	0			CRTS RELATED DISCREPANCY
	85-17-L0	REPORTABLE OCCU	R		0	CYM		LEAK IN AUX BLDG VENTILATION SYSTEM DUE TO MISSING SEAL PLATE IN HEPA FILTER SINCE MANUFACTURE
	85-19-L0	REPORTABLE OCCU	R		0	CYM		EXCESS COOLDOWN RATE AFTER HI PRESS RX TRIP DUE TO OPEN FEEDWATER HEATER RELIEF VALVES
	85-25-L2	REPORTABLE OCCU	R		0	WPA		LOSS OF ICB RX TRIP
	85-29-L0	REPORTABLE OCCU	R		0	WPA		EDG INOP = NOV 87-06
	85-27-L0	REPORTABLE OCCU	R		0	WPA		CONT AIR SEAL NOT TESTED IAW T/S =NOV 87-06
	85-28-L0	REPORTABLE OCCU	R		0	WPA		AFM PUMP AUTO START = NOV 87-06
	86-10-L0	REPORTABLE OCCU	0	8701	0	GYB		REDUNDANT CABLING IN THE SAME FIRE AREA
		REPORTABLE OCCU	0	8721	0	WPA		CRTS RELATED DISCREPANCY
	86-10-L1	REPORTABLE OCCU	0		0	WPA		APP "R" CABLES IN SAME FIRE ZONE

08/31/87

REGION 5
LICENSEE EVENT REPORT

PAGE 6

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	NAME	ACTION DATE	DESCRIPTIVE TITLE
50312	86-18-L1	REPORTABLE OCCU	R		0	WPA		DHS PUMP DRN LINE ELBOW WELD LEAK
	86-18-L1	REPORTABLE OCCU	R	8721	0	WPA		DHS TRIP-ARC IN BUMP LVL DETECTOR
	86-17-L0	REPORTABLE OCCU	R	8721	0	WPA		D/G AUTOMATIC LOADING DURING LBLOCA DID NOT ACCOUNT FOR APM RUN-OUT
	86-21-L0	REPORTABLE OCCU	R		0	ADH		FAILURE TO IMPLEMENT IN SERVICE TESTING OF CERTAIN SAFETY-RELATED VALVES
	86-21-L1	REPORTABLE OCCU	R		0	WPA		FAILURE TO IMPLEMENT 1ST OF CERTAIN SAFETY RELATED VALVES
	86-21-L2	REPORTABLE OCCU	E		0	WPA		FAILURE TO IMPLEMENT 1ST - SAFETY RELATED VALVES
	86-21-L3	REPORTABLE OCCU	0		0	WPA		FAILURE TO IMPLEMENT VLV 1ST
	86-22-L1	REPORTABLE OCCU	H		0	MIC		SAMPLES NOT TAKEN IN TIME DUE TO DISABLED NOBLE GAS SAMPLER
		REPORTABLE OCCU	H	8637	0			R15002 AUX BLDG STACK MONITOR INADVERTENTLY TAKEN OUT OF SERVICE- NO GAS GRAB SAMPLES WERE TAKEN
		REPORTABLE OCCU	H	8705	0			
	86-24-L0	REPORTABLE OCCU	R		0	WPA		DHS ISOL DURING INVERTER POWER TRANSFER
	86-25-L0	REPORTABLE OCCU	H	8705	0	MIC		SPENT FUEL POOL LEAK, REVIEW OF LICENSEE ACTIONS

08/31/87

REGION 5
LICENSEE EVENT REPORT

PAGE 7

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	NAME	ACTION DATE	DESCRIPTIVE TITLE
50312	86-26-L0	REPORTABLE OCCU	R		0	WPA		BFAS CALIB PROCEDURE DOES NOT ACCOUNT FOR ERROR OF TRIPPING BISTABLE
	86-28-L0	REPORTABLE OCCU	M		0	MIC		NOBLE GAS MONITOR SAMPLES NOT TAKEN IN MANNER REQUIRED BY THE TECHNICAL SPECIFICATIONS
	86-29-L0	REPORTABLE OCCU	M		0	MIC		NOBLE GAS MONITOR SAMPLES DILUTED ... REVIEW STATUS OF CORRECTIVE ACTIONS
	86-30-L0	REPORTABLE OCCU	R		0	WPA		DMS ISOL DURING XFORMER SWITCH
	86-32-L0	REPORTABLE OCCU	E		0	WPA		MISSED HOURLY FIRE WATCH
	87-02-L0	REPORTABLE OCCU	E		0	WPA		APPENDIX R DEFICIENCY-DB CIRCUITRY
	87-03-L0	REPORTABLE OCCU	E		0	WPA		FIRE WATCH POSTINGS NOT DONE WHEN WELDERS WENT ON BREAK
	87-06-L1	REPORTABLE OCCU	R	8721	0	WPA		MOV PROBLEMS - UPDATE
	87-06-L2	REPORTABLE OCCU	R		0	WPA		MOTOR OPERATED VLVS
	87-07-L0	REPORTABLE OCCU	E		0	WPA		POTENTIAL GENERIC PROBLEM-BAILEY 885 AUX RELAY MODULE LAMP SHORT TO GRND
	87-09-L0	REPORTABLE OCCU	M		0	MIC		INOPERABLE RADIATION MONITORS FOR REACTOR COOLANT LEAK DETECTION SYSTEM
	87-10-L0	REPORTABLE OCCU	R		0	WPA		APPENDIX R DEF- HI PT VENT VLVS

08/31/87

 REGION 5
 LICENSEE EVENT REPORT

PAGE 8

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	NAME	ACTION DATE	DESCRIPTIVE TITLE
50312	87-11-L0	REPORTABLE OCCU	E		0	WPA		SNURBER TEMPERATURE COMPENSATION CRITERIA
	87-11-L1	REPORTABLE OCCU	E		0	WPA		SNURBER # FOUND OUT OF TOLERANCE
	87-12-L1	REPORTABLE OCCU	E	8721	0	WPA		FAILURE TO PERFORM FIRE SUPPRESSION SYS SURV
	87-13-L0	REPORTABLE OCCU	0		0	WPA		REDUNDANT INST CABLES ROUTED IN SAME FIRE AREA
		REPORTABLE OCCU	0	8721	0			CRTS RELATED DISCREPANCY
	87-13-L1	REPORTABLE OCCU	0		0	WPA		INST CABLES ROUTED IN SAME FIRE AREA
	87-14-L0	REPORTABLE OCCU	E		0	WPA		INADEQUATE 1ST PROC
	87-15-L0	REPORTABLE OCCU	E		0	WPA		CO2 DELUGE SYSTEM DEACTIVATED
	87-16-L0	REPORTABLE OCCU	R		0	WPA		CABLES STORED IN ENERGIZED SAFETY-RELATED BREAKER CUBICLES
	87-17-L0	REPORTABLE OCCU	E		0	WPA		LLRT NOT PERFORMED ON CCM CTMT ISOLATION VALVES
	87-18-L0	REPORTABLE OCCU	M		0	MIC		WASTE GAS OXYGEN CONCENTRATION SURVEILLANCE NOT PERFORMED
	87-19-L0	REPORTABLE OCCU	E		0	WPA		FAILURE TO POST FIREWATCH

08/31/87

REGION 5
LICENSEE EVENT REPORT

PAGE 9

DUCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	NAME	ACTION DATE	DESCRIPTIVE TITLE
50312	87-21-L0	REPORTABLE OCCU	R		0	WPA		PRZR HTR DAMAGE
	87-23-L1	REPORTABLE OCCU	R		0	WPA		R&W TOTAL NEUT POWER RPS SIGNAL CHANNEL NOT ISOLATED
	87-25-L0	REPORTABLE OCCU	E		0	WPA		DECAY HEAT THERMAL RELIEF VALVES DID NOT MEET ASME SECTION CRITERIA DURING TESTING
	87-26-L0	REPORTABLE OCCU	0	8721	0	WPA		INTERMIXING OF POWER AND INST. CABLES - CRTS RELATED DISCREPANCY
	87-26-L1	REPORTABLE OCCU	0		0	WPA		MIXING OF POWER/CONTROL CABLES W/INSTRUMENT CABLES
	87-27-L0	REPORTABLE OCCU	R		0	WPA		SHUTDOWN BYPASS KEYS USED IN VIOL OF T/S
	87-28-L0	REPORTABLE OCCU	R		0	WPA		ACTION OF DG DUE TO SWITCHYARD OVERVOLTAGE CONDITION
	87-29-L0	REPORTABLE OCCU	E		0	WPA		FIRE PROT DEFICIENCIES
	87-30-L0	REPORTABLE OCCU	M		0	MIC		LESS THAN MINIMUM NUMBER OF HIGH RADIATION CHANNELS FOR REACTOR BUILDING PURGE SYSTEM
	87-31-L0	REPORTABLE OCCU	R		0	WPA		HYDROGEN PURGE T/S SURV NOT PERFORMED
	87-32-L0	REPORTABLE OCCU	R		0	WPA		INOPERABLE LTOP
	87-33-L0	REPORTABLE OCCU	E		0	WPA		MISSED FIREWATCH DURING SECURITY COMPUTER OUTAGE

08/31/87

REGION 5
LICENSEE EVENT REPORT

PAGE 10

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	NAME	ACTION DATE	DESCRIPTIVE TITLE
50312	87-34-L0	REPORTABLE OCCU	R		0	WPA		MPI MIN=FLO LINE DESIGN NON=SEISMIC
	87-35-L0	REPORTABLE OCCU	E		0	WPA		MISSED FIREWATCH DURING CO2 TEST
	87-36-L0	REPORTABLE OCCU	R		0	WPA		BLOCKAGE OF HRNG COOLER WTR SUPPLY AND RETURN LINES
	87-37-L0	REPORTABLE OCCU	R		0	WPA		HV TK LVL TS VIOL

08/31/87

REGION 5
LICENSEE EVENT REPORT

PAGE 11

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	NAME	ACTION DATE	DESCRIPTIVE TITLE
50512	82-01-X0	SPECIAL RPT.	0		0	TAY		FIRE WATCH NOT PERFORMED FOR THREE HOURS DUE TO AIRBORNE RADIOACTIVITY
		SPECIAL RPT.	0	8706	0	ADD		POSITIVE CONTROLS ARE NOT IN PLACE TO ASSURE THAT MINIMUM QUALIFIED STAFFING WILL BE ON SITE WEEKLY SURVEILLANCE OF NITROGEN BY8 FOUND KE-133 CONTAMINATION
	82-27-X1	SPECIAL RPT.	R		0			
	83-07-X0	SPECIAL RPT.	R	8708	0	JOA		HEAT TRACING P/HYDROGEN MONITORING SYSTEM FOUND DE-ENERGIZED
	83-09-X0	SPECIAL RPT.	R	8708	0	JOA		THERMAL SHIELDS NOT INSTALLED IN HYDROGEN MON SYSTEM HANGERS
	86-16-X0	SPECIAL RPT.	E		0	AOH		ABSTRACT OF ISI PROGRAM PERFORMED DURING 1985 REFUELING OUTAGE (SPECIAL REPORT)