

UNIT NAME Surry Unit 1
DATE 10/7/87
COMPLETED BY L. A. Warren
TELEPHONE 804-357-3184

REPORT MONTH September 1987

CORRECTED COPY

NO.	DATE	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	LICENSEE EVENT REPORT #	System Code ⁴	Component Code ⁵	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENT
87-06	9/5/87	F	0.0	A	1				Turbine Runback initiated by loss of Vitalous I-I caused by failure of Sola Transformer I-I. The transformer was repaired and will be re- placed by the new UPS system during the next refueling.
87-07	9/20/87	F	96.0	A	3	LER 87-024			Reactor trip, Safety Injection caused by failure of "B" RCP. Burnt leads repaired and pump RTS.
87-08	09-25-87	S	143.8	B	4				Plant maintained shutdown following outage related to 09-20-87 RCP maintenance. Scheduled additional outage time to work on maintenance backlog.

8711190336 871116
PDR ADDCK 05000280
PDR

- 1 F: Forced
S: Scheduled
- 2 Reason:
A - Equipment Failure (Explain)
B - Maintenance or Test
C - Refueling
D - Regulatory Restriction
E - Operator Training & License Examination
F - Administrative
G - Operational Error (Explain)
H - Other (Explain)
- 3 Method:
1 - Manual
2 - Manual Scram.
3 - Automatic Scram.
4 - Other (Explain)
- 4 Exhibit C - Instructions
for Preparation of Data
Entry Sheets for Licensee
Event Report (LER) File
(NUREG 0161)
- 5 Exhibit 1 - Same Source