



Log # TXX-7019
File # 10110
903.2
Ref. # 10CFR50.55(e)

William G. Council
Executive Vice President

November 30, 1987

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
CABLE TRAY WELDING PROCEDURES DEFICIENCY
SDAR: CP-87-78 (INTERIM REPORT)

Gentlemen:

On August 26, 1987, we verbally notified your Mr. H. S. Phillips of a potentially reportable item involving inadequate inspection procedures for cable tray welds. This is an interim report of a potentially reportable item under the provision of 10CFR50.55(e). Our latest interim report logged TXX-6748, was submitted on September 21, 1987.

We are continuing our evaluation of this item and are currently reviewing weld inspection documentation in order to determine what qualitative attributes are missing from the documentation.

We anticipate submitting our next report on this issue no later than March 24, 1987.

Very truly yours,

W. G. Council

W. G. Council

By: *J. S. Marshall*
J. S. Marshall
Supervisor,
Generic Licensing

DAR/grr

c - Mr. R. D. Martin, Region IV
Resident Inspectors, CPSES (3)

8712040270 871130
PDR ADOCK 05000445
S PDR

IE27
1/0