

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-373

As a result of the inspection conducted on April 25 through June 9, 1989, and in accordance with the "General Policy and Procedures for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1988), the following violation was identified:

10 CFR 50, Appendix B, Criterion XVI, requires that licensee's take prompt corrective actions to assure that conditions adverse to quality are promptly identified and corrected and that corrective actions are taken to preclude repetition.

Contrary to the above, on April 5, 1989, and again on April 19, 1989, the licensee failed to promptly identify the cause of the failure, and take corrective action to prevent recurrence, of the 1VR05YA reactor building ventilation isolation damper. Corrective action to prevent recurrence was not taken until April 24, 1989. In addition, the failure mechanism of the solenoid valves has been known since at least February 1985 but the licensee has not implemented corrective actions to prevent recurrence as of the date of the end of this inspection.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

6-20-89
Dated

W D Shafer
W. D. Shafer, Chief
Reactor Projects Branch 1