

NOTICE OF VIOLATION

Marymount Hospital

License No. 34-05382-01

As a result of the inspection conducted on June 21, 1989, and in accordance with 10 CFR Part 2, Appendix C - General Statement of Policy and Procedure for NRC Enforcement Actions (1988), the following violations were identified:

1. 10 CFR 35.51(a) requires that licensees calibrate the survey instruments used to show compliance with regulatory requirements before first use, annually, and following repair.

Contrary to the above, as of June 21, 1989, a Victoreen Serial Number 3196, survey instrument used to show compliance with regulatory requirements had not been calibrated since March 8, 1988.

This is a Severity Level IV violation (Supplement VI).

2. 10 CFR 35.70(f) requires that the weekly surveys for removable contamination required by 10 CFR 35.70(e) be conducted so as to be able to detect contamination on each wipe sample of 2,000 disintegrations per minute.

Contrary to the above, as of the date of inspection, June 21, 1989, the weekly surveys for contamination were not conducted so as to be able to detect contamination on each wipe sample of 2,000 disintegrations per minute. Specifically, Wipe test samples were conducted in counts per minutes.

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) the corrective actions that have been taken and the results achieved; (2) the corrective actions that will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated

July 5, 1989

Norman L. McElroy
Norman L. McElroy, Chief
Nuclear Materials Safety
Section 1