


Victoreen, Inc.



U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Allyn, IL. 60137

April 11, 1989


Subject: 10CFR21 Reportable Data, closure.


Dear Sir:

In accordance with VICTOREEN'S previous report (dated Jan. 27, 1989) the following corrective action has been taken.

Ref:b 3.vii The subject utility was supplied with a new PROM modified to correct the problem with the suspect PROM. A VICTOREEN Field Service Technician installed and tested the new PROM at GPU, TMI. The manual revisions were completed and forwarded to GPU at TMI.

Sincerely,


J. A. Smith, QA Manager


K. E. Stafford, Reliability Manager

6000 Cochran Road
Cleveland, Ohio 44130-3395
216) 248-9300
FAX 216) 248-9301
TELEX 810 421 6297

8905100199 890428
PDR ADOCK 05000341
P PDC

IE19
1/0