



# SAFEGUARDS INFORMATION

UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION II  
101 MARIETTA STREET, N.W.  
ATLANTA, GEORGIA 30323

Report Nos.: 50-250/89-03 and 50-251/89-03

Licensee: Florida Power and Light Company  
9250 West Flagler Street  
Miami, FL 33102

Docket Nos.: 50-250 and 50-251

License Nos.: DPR-31 and DPR-41

Facility Name: Turkey Point 3 and 4

Inspection Conducted: February 6-10, 1989

Inspector:

A. Tillman  
A. Tillman, Physical Security Inspector

5/8/89  
Date Signed

Approved by:

D. R. McGuire  
D. R. McGuire, Chief  
Physical Security Section  
Nuclear Materials Safety and Safeguards Branch  
Division of Reactor Safety and Safeguards

3/8/89  
Date Signed

## SUMMARY

Scope: This routine, unannounced inspection was limited to reactive inspection of licensee reported safeguards events and allegations of improprieties in security operational activities. Specific areas of inspection performed in response to the reported events and allegations included: Access Control to Protected and Vital Areas; Records and Reports; Compensatory Measures, and Protection of Safeguards Information.

Results: This reactive inspection of the Turkey Point Security Program identified significant weaknesses in communication and supervision at the shift level as demonstrated by delays in reporting security events to shift and site level security management; shift supervisors failing to ensure personnel compliance with duty assignments; and indecisive actions by shift supervisory personnel in response to questionable personnel actions and performance.

Within the areas inspected, the following violations were identified.

- (1) Failure to provide compensatory measures for a degraded Vital Area barrier.
- (2) Failure to provide adequate protection for Safeguards Information.

8903270347 890315  
PDR ADOCK 05000250  
Q PDC

Document transmitted herewith  
contains sensitive unclassified  
information. When separated from  
enclosures, this document is decontrolled.

# SAFEGUARDS INFORMATION