



Boston Edison
Pilgrim Nuclear Power Station
600 Rocky Hill Road
Plymouth, Massachusetts 02360

10 CFR 50.73

June 12, 1998
BECo Ltr. 2.98.075

L.J. Olivier
Senior Vice President Nuclear

U.S. Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, D.C. 20555

Docket No. 50-293
License No. DPR-35

The enclosed Licensee Event Report (LER) 98-010-00, "Inadequate Surveillance Performed for the Containment Cooling Flow Rate," is submitted in accordance with 10 CFR Part 50.73.

This letter contains the following commitment:

- Appropriate procedures will be revised to verify that the check valve forward flow exercise is tested to be greater than or equal to 5100 gpm. These procedures will be revised by August 1, 1998.

Please do not hesitate to contact me if there are any questions regarding this report.

L.J. Olivier *Ter 2*
L.J. Olivier

KRD/dcg
Enclosure: LER 98-010-00

9806220132 980612
PDR ADOCK 05000293
S PDR

cc: Mr. Hubert J. Miller
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Sr. NRC Resident Inspector - Pilgrim Station

INPO Records
700 Galleria Parkway
Atlanta, GA 30339-5957

Standard BECo LER Distribution