

Commonwealth Edison Company
LaSalle Generating Station
2601 North 21st Road
Marseilles, IL 61341-9757
Tel 815-357-6761



June 26, 1998

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Licensee Event Report #97-026-01, Docket #050-373 is being submitted to your office in accordance with 10 CFR 50.73(a)(2)(i).

Attachment A provides the commitment(s) for this submittal.

If there are any questions or comments concerning this letter, please refer them to Harold D. Pontious, Jr., Regulatory Assurance Manager, at (815) 357-6761, extension 2383.

Respectfully,

A handwritten signature in dark ink, appearing to read "Fred R. Dacimo", is written over a faint circular stamp.

Fred R. Dacimo
Site Vice President
LaSalle County Station

Enclosures: Regulatory Commitment(s) - Attachment A
Licensee Event Report

cc: C. A. Paperiello, Acting NRC Region III Administrator
M. P. Huber, NRC Senior Resident Inspector - LaSalle
F. Niziolek, IDNS Senior Reactor Analyst
INPO - Records Center

9806300548 980626
PDR ADOCK 05000373
S PDR

ATTACHMENT A
REGULATORY COMMITMENT(S)

The following identifies those actions committed to by ComEd in this document. Any other actions discussed in this submittal represent intended or planned actions by ComEd. They are described to the NRC for the NRC's information and are not regulatory commitments.

<i>Regulatory Commitment(s)</i>	<i>Tracking Number</i>
A procedure to perform a logic systems functional test on the rod block logic will be developed.	NTS# 373-180-97-SCAQ00026S101
LOS-RM-M1, Scram Discharge Volume Scram Bypass Switch Rod Block Functional Test will be revised to include testing of both activity controllers.	NTS# 373-180-97-SCAQ00026.24
LFS-100-1, Refueling Platform (Bridge) Main Hoist Interlocks Check for Core Alterations will be revised to include testing of both activity controllers.	NTS# 373-180-97-SCAQ00026S102
LFS-100-2, Refueling Platform (Bridge) Frame Hoist Interlocks Check for Core Alterations will be revised to include testing of both activity controllers.	NTS# 373-180-97-SCAQ00026S103
LFS-100-3, Refueling Platform (Bridge) Mono-Hoist Interlocks Check for Core Alterations will be revised to include testing of both activity controllers.	NTS# 373-180-97-SCAQ00026S104