



- NOTES:
1. OVER-823A, B, C, AND D SHOULD BE WITHIN THREE FEET OF TANK LEVELS.
  2. VALVES RELIEF VALVES MUST BE LIMITED TO BE PROVIDED WITH LEADS TO PREVENT EXCESS ACCUMULATION.
  3. THE LEAD FOR EACH RELIEF VALVE SHOULD BE LOCATED IN A LOW POSITION TO ALLOW DRAINING THE LOCAL AREA WITH COMMERCIAL WATER. A SPECIAL CLAPPED APERTURE VALVE SHOULD BE INSTALLED UPSTREAM OF THE TROUBLE. THE TROUBLE MUST BE REPAIRABLE AS LONG AS ONE "TRAP" LEADS TO BE PROVIDED BETWEEN THE I.C. VALVE AND THE OPENING VALUE OF THE TROUBLE FOR EACH RELIEF VALVE.

**30X**

**POOR ORIGINAL**

**PRC APERTURE CARD**

NO. 428	REV. 1	DATE	BY
NO. 428	REV. 2	DATE	BY
NO. 428	REV. 3	DATE	BY
NO. 428	REV. 4	DATE	BY
NO. 428	REV. 5	DATE	BY

**BECHTEL**  
 4800 AVENUE  
 MIDLAND PLANT UNITS 1 & 2  
 CONSUMERS POWER COMPANY  
 PIPING AND INSTRUMENT DIAGRAM  
 BORON RECOVERY  
 UNIT 1 & 2

JOB NO.	DRAWING NO.	REV.
7220	M-408 SH 3A	3

17"  
 8.5"  
 8.5"  
 11"  
 17"

17"  
 8.5"  
 8.5"  
 11"  
 17"



RIDS

8302090557

