



February 15, 2021  
L-2021-042  
10 CFR 50.55a

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555-00001

Re: Turkey Point Unit 4  
Docket No. 50-251  
Inservice Inspection Program  
Owner's Activity Report (OAR-1)

Attached find the Owner's Activity Report (Form OAR-1), for Turkey Point Unit 4 (PTN 4-32), Fifth Inservice Inspection Interval-Second, and IWE Third Interval-First. The Form OAR-1, Owner's Activity Report, implements Code Case N-532-4.

Should there be any questions concerning this report, please contact Mr. Robert J. Hess, Licensing Manager, at 305-246-4112.

Sincerely,

A handwritten signature in black ink, appearing to read 'R. Hess', with a long horizontal line extending to the right.

Robert J. Hess  
Licensing Manager  
Turkey Point Nuclear Plant

Attachment

cc: Regional Administrator, Region II, USNRC  
Senior Resident Inspector, USNRC, Turkey Point Plant

**FORM OAR-1 OWNER'S ACTIVITY REPORT**

Report Number: ISI-PTN-4-2020

Plant: Turkey Point Nuclear Power Plant Unit 4  
9760 SW 344th Street  
Homestead, Florida 33035

Commercial Service Date: September 7, 1973 Refueling Outage No.: PTN 4-32

Current Inspection Interval: ISI-Fifth and IWE-Third

Current Inspection Period: ISI Fifth Interval-Second and IWE Third Interval -First

Edition and Addenda of Section XI applicable to the inspection plans: ISI Fifth Interval-2007 Edition through the 2008 Addenda and IWE Third Interval-2007 Edition through the 2008 Addenda

Date and Revision of inspection plans: ISI Fifth Interval Effective-January 7, 2020 Rev.2 and IWE-July 15, 2018 Rev.0

Edition and Addenda of Section XI applicable to repairs and replacements, if different than the inspection plan: ASME Section XI 2007 Edition through 2008 Addenda.

Code Cases Used: N-532-5

**CERTIFICATE OF CONFORMANCE**


I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the Inspection plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of PTN4-32 conform to the requirements of Section XI.

Signed  Engineering Programs Manager Date 2/3/21  
Owner or Owner's Designee, Title

**CERTIFICATE OF INSERVICE INSPECTION**

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and employed by the Hartford Steam Boiler Inspection and Insurance Company of Connecticut have inspected the items described in this Owner's Activity Report, and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the inspector nor his employer shall be liable in any manner for any personal injury or property damage or loss of any kind arising from or connected with this inspection.

 Commissions NB14292 R,N,I  
Inspector's Signature National Board Number and Endorsement

Date 2/11/2021

FORM OAR-1 OWNER'S ACTIVITY REPORT

---

<b>TABLE 1 ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT REQUIRED EVALUATION FOR CONTINUED SERVICE</b>		
<b>Examination Category and Item Number</b>	<b>Item Description</b>	<b>Evaluation Description</b>
None	None	None

FORM OAR-1 OWNER'S ACTIVITY REPORT

<b>TABLE 2</b>  <b>ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES</b>  <b>REQUIRED FOR CONTINUED SERVICE</b>				
Code Class	Item Description	Description Of Work	Date Completed	Repair/Replacement Plan Number
3	Component Cooling Water Pipe	Install PM Cap on A CCW supply pipe due to wall loss	10/20/20	RR40676550-09
3	Component Cooling Water Pipe	Install PM Cap on B CCW return pipe due to wall loss	10/30/20	RR40676550-03
3	Component Cooling Water Pipe	Install PM Cap on A CCW return pipe due to wall loss	10/20/20	RR40676550-02
3	Component Cooling Water Pipe	Install PM Cap on B CCW supply pipe due to wall loss	10/30/20	RR40676550-01
2	Containment Spray Elbow	Replace Containment Spray CS Elbow with SS due to corrosion	10/22/20	RR40735938-01
3	Component Cooling Water Pipe	Weld Repair Pin Hole Leak on B CCW PM Cap	11/6/20	RR40676550-15
2	Containment Penetration P-48B	Welding Support for Replacement of Penetration P-48B Insulator	11/2/20	RR40747435-03
1	Valve 4-312A	Replace valve 4-312A	10/19/20	RR40656497-01