

COHEN & GRIGSBY, P.C.

ATTORNEYS AT LAW

11 STANWIX STREET
15TH FLOOR

PITTSBURGH, PENNSYLVANIA 15222-1319

JENNIFER M. PALMER
Direct Dial: (412) 297-4865
E-Mail: jpalmer@cohenlaw.comTELEPHONE (412) 297-4900
FAX (412) 209-0672**FOIA/PA REQUEST**

Case No:

79-364

Date Rec'd:

9-17-99

Action Off:

POOL

Related Case:

September 15, 1999

Russell A. Powell
The Freedom of Information Act/
Privacy Act Officer
FOIA/LPDR Branch
U. S. Nuclear Regulatory Commission
Mail Stop T-6 D8
Washington, D.C. 20555-0001Re: FOIA Request regarding large and small bore piping, and Stone
& Webster Engineering Corporation

Dear Mr. Powell:

In accordance with The Freedom of Information Act, 5 U.S.C. 552, and the provisions of 10 CFR Part 9, as amended, we request copies of any documents in your possession which relate to any or all of the following descriptions:

1. All documents submitted by Stone & Webster Engineering Corporation or the licensee regarding Surry 1 and 2, Maine Yankee, Fitzpatrick, or Beaver Valley Power Station No. 1 in response to I.E. Bulletin 79-14 concerning small bore piping (piping 2 ½ inches or less in diameter).
2. All documents submitted by Stone & Webster Engineering Corporation or the licensee regarding Surry 1 and 2, Maine Yankee, Fitzpatrick, or Beaver Valley Power Station No. 1 in response to I.E. Bulletins 79-02 or 79-14 concerning large bore piping seismic capability or seismic stress analysis (piping 2 ½ inches or more in diameter).
3. All documents from whatever source regarding revisions, amendments or changes to I.E. Bulletin 79-14.

COHEN & GRIGSBY, P.C.

Mr. Russell A. Powell

September 15, 1999

Page 2

4. All documents pertaining to "reportable incidents" (including Licensee Event Reports or "LER"s) involving Category I piping, and, in particular, piping supports at Surry 1 and 2, Maine Yankee, Fitzpatrick, or Beaver Valley Power Station No. 1.
5. All documents pertaining to the NRC's meetings with Stone & Webster Engineering Corporation between October 1978 and March 1979 regarding the adequacy of computer analyzed piping and possibility of a shutdown.
6. All specifications, drawings or other documentation pertaining to the design basis for the Category I small bore piping at Surry 1 and 2, Maine Yankee, Fitzpatrick, or Beaver Valley Power Station No. 1.
7. Any documentation pertaining to a review conducted in 1974 or 1975 at Beaver Valley Power Station No. 1 to confirm the as-built conditions of the Category I small bore piping.
8. All file materials, notes, records and other documents created or maintained by the following individuals pertaining to the shutdown of Beaver Valley Power Station No. 1, Maine Yankee, Surry 1 and 2, and Fitzpatrick:
 - (a) R. Bosnak
 - (b) E. Case
 - (c) H. Denton
 - (d) D. Eisenhut
 - (e) B. Grimes
 - (f) K.S. Herring
 - (g) J. Knight
 - (h) R. Mattson
 - (i) V. Noonan
 - (j) W. Russell
 - (k) L.C. Shao
 - (l) V. Stello

COHEN & GRIGSBY, P.C.

Mr. Russell A. Powell

September 15, 1999

Page 3

This request includes, but is not limited to, all documents in the files of your office, all related correspondence, and all reports, findings and recommendations. This request also includes, but is not limited to, all documents produced by or obtained from Stone & Webster Engineering Corporation or any licensee or construction permit holder for Surry 1 and 2, Maine Yankee, Fitzpatrick, or Beaver Valley Power Station No. 1.

Pursuant to 10 CFR § 9.35, as amended, we will assume financial responsibility for all fees as set out in the Commission's current schedule of fees. We ask that you respond to this request within twenty (20) business days. If you have any questions, or require any additional information or clarification, please let us know.

Very truly yours,

COHEN & GRIGSBY, P.C.

By 
Jennifer M. Palmer

<<NUDOCS/AD>>

Nuclear Regulatory Commission

ADQ42 V6.3.23.0

==== TCON21 ===== Accession Number - 7906290824 ===== Start ===== End ===

*Availability: PDR Format: * Microfilm Address: 02172-153 02172-155

Size: 3pp.

Document Type: Incoming Correspondence

Issued: 780905

Desc/: Comments on proposed rulemaking 10CFR20:acceptance of rebuttal of

Title: Rothman as satisfactory response to Journal of American Medical
: Association article is further indication of NRC incompetence.

Authors: BERTELL,R.

Affiliation Not Assigned

Recipients: FELTON,J.M.

Division of Rules & Records (ADM, Pre 870413)

Dockets:

781027

Docket Date

File Locations: PDR FOIA * WILLIAMS81-77 810409 Package: 7906290824 #
PDR PRM * 20-6A 780905 8104160677 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOCS/AD>>

Nuclear Regulatory Commission

ADQ42 V6.3.23.0

==== TCON21 ===== Accession Number - 7910040364 ===== Start ==== End ===

Availability: PDR Format: * Microfilm Address: 01095-095 01095-102

Size: 8pp.

Document Type: Orders

Issued: 790810

Desc/: Draft order lifting suspension of facility operation required by

Title: 790313 show cause order.Requires mods to all piping sys equipment

: nozzles,containment penetrations & supports in inaccessible areas

: prior to startup.

Authors: MATTSON,R.J. Office of Nuclear Reactor Regulation, Director

Recipients:

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe
05000333 50-333 James A. FitzPatrick Nuclear Power Plant, Power Autho

File Locations: PDR ADOCK 05000280 G

790810 Package: 7910040357 A

PDR ADOCK 05000333 G

790810

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOLCS/HD>> Nuclear Regulatory Commission NUDG42 V0.3.23.0
==== TCON21 ===== Accession Number - 7906290709 ===== Start ==== End ===
Availability: PDR Format: * Microfilm Address: 18385-298 18385-300
Size: 3pp.

Document Type: Outgoing correspondence Issued: 790518
Desc/: Lists subj of 790514 & 18 info requests re amplified response spectra
Title: using soil structure interaction. Response should be completed by
: 790523.

Authors: STELLO,V. Division of Operating Reactors

Recipients: PROFFITT,W.L. Virginia Power (Virginia Electric & Power Co.)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe
05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

File Locations: PDR ADOCK 05000280 P 790518 Package: 7906290709 #
PDR ADOCK 05000281 P 790518

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOLCS/AD>> Nuclear Regulatory Commission HDQ42 V6.3.23.0
==== TCON21 Accession Number - 7909180241 Start End ==
Availability: PDR Format: * Microfilm Address: 00959-320 00959-328
Size: 9pp.

Document Type: Orders Issued: 790806
Desc/: Draft order lifting suspension of facility operation required by
Title: 790313 show cause order.

Authors: DENTON,H.R. Office of Nuclear Reactor Regulation, Director

Recipients:

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

File Locations: PDR ADOCK 05000280 G 790806 Package: 7909180237 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NDD0003/ND>> NUCLEAR REGULATORY COMMISSION NDDQ42 V0.3.23.0
==== TCON21 ===== Accession Number - 7909170568 ===== Start ==== End ===
Availability: PDR Format: * Microfilm Address: 00957-128 00957-154
Size: 2pp.

Document Type: Outgoing correspondence Issued: 790822
Desc/: Forwards NRC 790822 order lifting 790313 order to show cause. Earlier
Title: order suspended due to reanalysis & mod of piping deficiencies in
: safety-related sys. Unit can withstand seismic event.

Authors: DENTON, H.R. Office of Nuclear Reactor Regulation, Director

Recipients: PROFFITT, W.L. Virginia Power (Virginia Electric & Power Co.)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Power

Internal Tracking # TAC 54253

File Locations: PDR ADOCK 05000280 G

790822 Package: 7909170568 *

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDDUCS/HD>>

Nuclear Regulatory Commission

HDQ42 V6.3.23.0

==== TCON21 ===== Accession Number - 7907190048 ===== Start ===== End =====

Availability: PDR Format: *

Microfilm Address: 02092-001 02092-004

Size: 3pp.

Document Type: Outgoing correspondence

Issued: 790522

Desc/: Responds to ltr re NRC 790313 orders to shut down plants. NRC prefers

Title: to review situation in expedited & disciplined manner & return plants
: to operation w/no threat to public health & safety.

Authors: DENTON,H.R.

Office of Nuclear Reactor Regulation, Director

Recipients: BEAN,J.

Affiliation Not Assigned

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe
05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

File Locations: PDR ADOCK 05000309 H

790522 Package: 7907190048 *

There Is Not A Text Or Abstract File Available For Viewing.

Count: *0

<Replace>

<<NUDOLCS/HD>>

Nuclear Regulatory Commission

HDQ42 v6.3.23.0

==== TCON21 ===== Accession Number - 7907120408 ===== Start ===== End =====

Availability: PDR Format: *

Microfilm Address: 18387-052 18387-055

Size: 2pp.

Document Type: Outgoing correspondence

Issued: 790501

Desc/: Responds to 790320 ltr to JM Hendrie re pipestress reanalysis.Explains

Title: seismic analyses techniques to be used while plants are shutdown.

:
:

Authors: DENTON,H.R.

Office of Nuclear Reactor Regulation, Director

Recipients: COLMAN,M.

Virginia, Commonwealth of

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

File Locations: PDR ADOCK 05000280 P

790501 Package: 7907120408 *

PDR ADOCK 05000281 P

790501

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

==== TCON59 ===== Accession Number - 7906110408 ===== Start ===== End ===

Availability: PDR Format: *

Microfilm Address: 18385-028 18385-031

Size: 5pp.

Document Type: Internal or external memorandum Issued: 790501

Desc/: Forwards draft of proposed responses to 790319 ltr from 10 VA

Title: congressional delegates re pipe stress analysis at facility.

:
:
:

Authors: DENTON,H.R. Office of Nuclear Reactor Regulation, Director

Recipients: GILINSKY,V. Commissioners (NRC, Post 750119)

HENDRIE,J.M. Commissioners (NRC, Post 750119)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

File Locations: PDR ADOCK 05000280 U

790521 Package: 7906110367 J

PDR ADOCK 05000281 U

790521

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

==== TCON59 ===== Accession Number - 7904110072 ===== Start ===== End ==

Availability: PDR Format: * Microfilm Address: 03445-122 03445-123

Size: 2pp.

Document Type: Outgoing correspondence

Issued: 790329

Desc/: Forwards QA program approval for radioactive package.

Title:

Authors: MACDONALD,C.E. Transportation Certification Branch (NMSS, Pre 87041

Recipients: SHIMSHAK,R.E. Dairyland Power Cooperative

Dockets: 07100025 71-0025 Dairyland Power Cooperative

File Locations: PDR ADOCK 07100025 C

790329 Package: 7904110072 #

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOCS/AD>>

Nuclear Regulatory Commission

ADQ42 V6.3.23.0

==== TCON59 ===== Accession Number - 7909180237 ===== Start ==== End ===

Availability: PDR Format: *

Microfilm Address: 00959-319 00959-344

Size: 1p.

Document Type: Internal or external memorandum

Issued: 790806

Desc/: Forwards draft order & safety evaluation re resumption of facility

Title: operation.

Authors: DENTON, H.R.

Office of Nuclear Reactor Regulation, Director

Recipients: GILINSKY, V.

Commissioners (NRC, Post 750119)

HENDRIE, J.M.

Commissioners (NRC, Post 750119)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

File Locations: PDR ADOCK 05000280 G

790806 Package: 7909180237 *

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOCs/AD>>

Nuclear Regulatory Commission

HDQ42 V6.3.23.0

==== TCON21 ===== Accession Number - 7902020237 ===== Start ===== End =====

Availability: PDR Format: *

Microfilm Address: 15087-139 15087-140

Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 790129

Desc/: LER 78-041/03X-1 on 781121:during performance of PT-39-1 at full

Title: power,snubber 1-WAPD-HSS-141B had 0 fluid level in reservoir,due to
: crack in reservoir glass.
:

Authors: STEWART,W.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 78-041

File Locations: PDR ADOCK 05000280 S

790130 Package: 7902020230 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDUCS/HD>>

Nuclear Regulatory Commission

HDQ42 V6.3.23.0

==== TCON21 ===== Accession Number - 7902060322 ===== Start ==== End ===

Availability: PDR Format: * Microfilm Address: 15087-133 15087-137

Size: 1p.

Document Type: Incoming Correspondence

Issued: 790202

Desc/: Forwards LER 78-031/03X-1 & 78-038/03X-1.

Title:

:
:
:

Authors: STALLINGS,C.M. Virginia Power (Virginia Electric & Power Co.)

Recipients: O'REILLY,J.P. Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Other Related Number 062

File Locations: PDR ADOCK 05000280 S

790202 Package: 7902060322 *

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDUCS/HD>> Nuclear Regulatory Commission HDQ42 V6.3.23.0
==== TCON21 ===== Accession Number - 7902260418 ===== Start ==== End ===
Availability: PDR Format: * Microfilm Address: 15087-126 15087-128
Size: 1p.

Document Type: Incoming Correspondence Issued: 790221
Desc/: Forwards LER 79-003/03L-0.
Title:

Authors: STALLINGS,C.M. Virginia Power (Virginia Electric & Power Co.)

Recipients: O'REILLY,J.P. Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

File Locations: PDR ADOCK 05000280 S 790221 Package: 7902260418 *

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission HDQ42 V6.3.23.0
==== TCON21 ===== Accession Number - 7903270419 ===== Start ==== End ===
Availability: PDR Format: * Microfilm Address: 15087-118 15087-119
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 790322
Desc/: LER 79-004/01T-0 on 790309:util was notified of possible
Title: non-conservatisms in pipe stress code used to analyze piping sys.Units
: shutdown awaiting results of re-evaluation.

Authors: STEWART,W.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe
Licensee Event Rpt # 79-004

File Locations: PDR ADOCK 05000280 S 790322 Package: 7903270414 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOLCS/HD>>

Nuclear Regulatory Commission

ADQ42 V6.3.23.0

==== TCON21 ===== Accession Number - 7904240366 ===== Start ===== End =====

Availability: PDR Format: *

Microfilm Address: 15079-359 15079-360

Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 790418
Desc/: LER 79-010/03L-0 on 790323:while in cold shutdown, discrepancies found
Title: in location & configuration of pipe supports.Caused by const
: deficiencies & util maint.Necessary repairs will be made prior to
: startup.

Authors: STEWART,W.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 79-010

File Locations: PDR ADOCK 05000280 S

790419 Package: 7904240361 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDUCS/HD>>

Nuclear Regulatory Commission

HDQ42 V6.3.23.0

==== TCON21 ===== Accession Number - 7908030456 ===== Start ==== End ===

Availability: PDR Format: *

Microfilm Address: 00421-245 00421-248

Size: 4pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 790731
Desc/: LER 79-004/01X-1 on 790309:notification received of possible errors in
Title: pipe stress code analyses in some facility piping sys.Inaccurate value
: weights were also identified. Plants are shut down pending evaluation.

Authors: STEWART,W.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 79-004

File Locations: PDR ADOCK 05000280 S

790801 Package: 7908030448 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NDDUCS/ND>> NUCLEAR REGULATORY COMMISSION NDQ42 V6.3.23.0
==== TCON21 Accession Number - 7910230461 Start ==== End ===
Availability: PDR Format: * Microfilm Address: 01200-276 01200-277
Size: 2pp.

Document Type: Licensee Event Report (See also AO,R0) Issued: 791017
Desc/: LER 79-027/01T-0:on 791003,review in response to IE Bulletin 79-14
Title: indicated three bypass lines & one safety injection line w/stresses in
 : excess of allowable limits.Caused by inaccurately installed piping
 : line supports.Mod to be made.
Authors: STEWART,W.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe
Licensee Event Rpt # 79-027

File Locations: PDR ADOCK 05000280 S 791018 Package: 7910230460 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

==== TCON21 ===== Accession Number - 7910310280 ===== Start ==== End ===
Availability: PDR Format: * Microfilm Address: 01247-288 01247-289
Size: 2pp.

Document Type: Licensee Event Report (See also R0,R0) Issued: 791102
Desc/: LER 79-028/03L-0:on 791003,concluded that ten of 209 anchor bolts
Title: inspected failed to meet acceptance criteria.Caused by improper
: installation.Deficiencies corrected as required.

Authors: STEWART,W.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe
Licensee Event Rpt # 79-028

File Locations: PDR ADOCK 05000280 S

791029 Package: 7910310278 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 7910310352 ===== Start ===== End ===
Availability: PDR Format: * Microfilm Address: 01245-037 01245-042
Size: 6pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 791029
Desc/: Update to LER 79-004/01X-2:on 790309,A/E notified util of possible
Title: nonconservatism in pipe stress code used to analyze piping sys & of
: innaccurate valve weights used by error in pipe stress analysis &
: valve weight.

Authors: STEWART,W.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 79-004

File Locations: PDR ADOCK 05000280 S 791029 Package: 7910310342 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission HDQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 7911140357 ===== Start ===== End ===
Availability: PDR Format: * Microfilm Address: 01331-103 01331-104
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 791106
Desc/: LER 79-029/01T-0:on 791011,at cold shutdown,min wall thickness
Title: violation discovered in reducers mating w/MOV-1842.Caused by const
: deficiency.Reducers replaced & verified to meet min wall thickness
: criteria.
Authors: STEWART,W.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe
Licensee Event Rpt # 79-029

File Locations: PDR ADOCK 05000280 S 791106 Package: 7911140354 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDUCS/HD>>

NUCLEAR REGULATORY COMMISSION

HDQ42 VOL 5.23.0

==== TCON59 ===== Accession Number - 7911200500 ===== Start ===== End ===

Availability: PDR Format: * Microfilm Address: 01367-172 01367-174

Size: 3pp.

Document Type: Incoming Correspondence Issued: 791024
Desc/: Responds to IE Bulletin 79-23, "Potential Failure of Emergency Diesel
Title: Generator Field Exciter Transformer." Diesel generators sustained
: full-load operation test, Primaries of excitation transformers are
: ungrounded.

Authors: HERBEIN, J.G. Metropolitan Edison Co.

Recipients: GRIER, B.H. Region I, RI (IE, 720101-810228)

Dockets: 05000289 50-289 Three Mile Island Nuclear Station, Unit 1, General Pu

Internal Tracking # IEB-79-23

File Locations: PDR ADOCK 05000289 Q

791024 Package: 7911200500 #

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDDUCS/HD>>

NUCLEAR REGULATORY COMMISSION

HDQ42 V6.3.23.0

==== TCON59 ===== Accession Number - 8001020490 ===== Start ==== End ===

Availability: PDR Format: *

Microfilm Address: 01679-185 01679-186

Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 791228
Desc/: LER 79-040/01T-0:on 791218,pipe stress reanalysis of show cause lines
Title: outside containment determined that feed header to nonregenerative &
: seal water heat exchangers overstressed beyond 50% ultimate
: capacity.Mods initiated.

Authors: STEWART,W.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 79-040

File Locations: PDR ADOCK 05000280 S

791227 Package: 8001020482 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOLCS/HD>> Nuclear Regulatory Commission HDQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8001040554 ===== Start ===== End ===
Availability: PDR Format: * Microfilm Address: 01685-091 01685-092
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 800102
Desc/: LER 79-042/01T-0:on 791220,as result of pipe stress reanalysis on show
Title: cause lines outside containment,support on line 10 CC-143-121 found to
: be overstressed beyond 50% ultimate capacity.Cause not stated.Mod
: completed.

Authors: STEWART,W.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 79-042

File Locations: PDR ADOCK 05000280 S 800102 Package: 8001040550 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/HD>> Nuclear Regulatory Commission HDQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8001250498 ===== Start ===== End ===
Availability: PDR Format: * Microfilm Address: 01809-197 01809-198
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 800122
Desc/: LER 80-001/03L-0:on 800101,w/unit at cold shutdown,snubber
Title: 1-WFPD-HSS-14 found w/empty reservoir & declared inoperable per Tech
: Spec.Caused by leakage around pipe nipple threads on valve block &
: extended seal washers.Snubber replaced.
Authors: STEWART,W.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe
Licensee Event Rpt # 80-001

File Locations: PDR ADOCK 05000280 S 800122 Package: 8001250493 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/HD>>

Nuclear Regulatory Commission

HDQ42 v6.3.23.0

==== TCON59 ===== Accession Number - 8002190729 ===== Start ==== End ===

Availability: PDR Format: *

Microfilm Address: 04019-331 04019-332

Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 800214
Desc/: LER 80-010/01T-0:on 800131,pipe stress reanalysis revealed overstress
Title: on line 18"-CC-9-121,Unit 2 supply to RHR exchanger A.Caused by
: inadequacy of supports.Mod completed prior to final stress
: calculation.

Authors: STEWART,W.J. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 80-010

File Locations: PDR ADOCK 05000280 S

800214 Package: 8002190722 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDDULS/AD>> Nuclear Regulatory Commission HDQ42 v6.3.23.0
==== TCON59 ===== Accession Number - 8003040650 ===== Start ==== End ===
Availability: PDR Format: * Microfilm Address: 04132-361 04132-362
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 800303
Desc/: LER 80-018/01T-0:on 800219,pipe stress reanalysis on IE Bulletin 79-14
Title: lines revealed overstressed condition on piping penetrations would
 : exist during DBE.Addl constraints designed & will be installed.
 :

Authors: STEWART,W.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Internal Tracking # IEB-79-14
Licensee Event Rpt # 80-018

File Locations: PDR ADOCK 05000280 S 800228 Package: 8003040640 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDULS/HD>>

Nuclear Regulatory Commission

ADQ42 V6.3.23.0

==== TCON59 ===== Accession Number - 8004280616 ===== Start ==== End ===

Availability: PDR Format: *

Microfilm Address: 04697-342 04697-343

Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 800424
Desc/: LER 80-021/03L-0:on 800327,during performance of 1-PT-39B-1, snubber
Title: 1-WAPD-HSS-148 discovered w/low fluid level in reservoir.Caused by
: fluid leaking out through reservoir to block tube fitting.Snubber
: declared inoperable.

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 80-021

File Locations: PDR ADOCK 05000280 S

800424 Package: 8004280612 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8004280626 ===== Start ===== End =====
Availability: PDR Format: * Microfilm Address: 04697-344 04697-344
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 800424
Desc/: LER 80-022/03L-0:on 800327,during performance of 1-PT-39B-1, snubbers
Title: 1-RC-HSS-116 & 1-RC-HSS-117 discovered installed 90 degrees out of
: position.Caused by corrective work performed per IE Bulletin 79-14.
:

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Internal Tracking # IEB-79-14
Licensee Event Rpt # 80-022

File Locations: PDR ADOCK 05000280 S 800424 Package: 8004280612 B

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/AD>>

Nuclear Regulatory Commission

ADQ42 V6.3.23.0

==== TCON59 ===== Accession Number - 8007280625 ===== Start ===== End =====

Availability: PDR Format: *

Microfilm Address: 06001-355 06001-356

Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 800724
Desc/: LER 80-041/03L-0:on 800625,pipe stress re-analysis indicated baseplate
Title: anchor bolts on hanger H-2 on line 12 inch -CC-27- 121 & hanger H-9 on
: line 12 inch-CC-33-121 overstressed. Mods to anchor bolts complete.
:

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 80-041	800625	Event Date
-----------------------------	--------	------------

File Locations: PDR ADOCK 05000280 S 800724 Package: 8007280625 #

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

==== TCON59 ===== Accession Number - 8011030433 ===== Start ==== End ===

Availability: PDR Format: * Microfilm Address: 06855-097 06855-099

Size: 3pp.

Document Type: Licensee Event Report (See also AO,R0) Issued: 801027
Desc/: Updated LER 79-012/03X-1:on 790402,during shutdown functional test of
Title: 74 snubbers revealed 21 not meeting design criteria.Caused by snubbers
: not being readjusted to design conditions.Units reset.
:

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 79-012 790402 Event Date

File Locations: PDR ADOCK 05000280 S 801027 Package: 8011030432 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8104020621 ===== Start ===== End ===
Availability: PDR Format: * Microfilm Address: 08104-127 08104-128
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 810327
Desc/: Updated LER 80-010/01X-1:on 800131,overstress on 18-inch line
Title: CC-9-121,unit 2 supply to RHR exchanger,found during pipe stress
: reanalysis on show cause lines.Caused by supports installed to prevent
: overstress during DBE.
Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 80-010 800131 Event Date

File Locations: PDR ADOCK 05000280 S 810327 Package: 8104020600 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8104020648 ===== Start ==== End ===
Availability: PDR Format: * Microfilm Address: 08104-133 08104-134
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 810327
Desc/: Updated LER 80-022/03X-1:on 800327,snubbers 1-RC-HSS-116 &
Title: 1-RC-HSS-117 found out of position during inaccessible snubbers visual
: insp 1-PT-39B-1.Caused by improper installation due to design change
: deficiency.
Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)
Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Internal Tracking #	IEB-79-14	800327	Event Date
Licensee Event Rpt #	80-022		

File Locations: PDR ADOCK 05000280 S 810327 Package: 8104020600 D

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8110290476 ===== Start ==== End ===
Availability: PDR Format: * Microfilm Address: 10387-012 10387-013
Size: 2pp.

Document Type: Licensee Event Report (See also AO,R0) Issued: 811019
Desc/: LER 81-055/03L-0:on 810925,snubber 1-WGCB-HSS-03 on B steam generator
Title: blowout line was not inspected during PT-39A-2. Caused by inadvertent
: omission from updated periodic test data sheet.Snubber inspected &
: added to sheet.

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region 2, Ofc of the Director (810301-820201)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt #	81-055	810925	Event Date
----------------------	--------	--------	------------

File Locations: PDR ADOCK 05000280 S 811019 Package: 8110290466 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDDOCS/HD>>

NUCLEAR REGULATORY COMMISSION

HDQ42 V6.3.23.0

==== TCON59 ===== Accession Number - 8111120605 ===== Start ===== End ===

Availability: PDR Format: *

Microfilm Address: 10794-076 10794-078

Size: 3pp.

Document Type: Incoming Correspondence

Issued: 740412

Desc/: Suppls util 740118 motion to extend CPPR-62 completion date. Requests

Title: extension until 750301 to account for limited accuracy for
: predictions.

Authors: CAHILL,W.J.

Consolidated Edison Co. of New York, Inc.

Recipients: O'LEARY,J.F.

Atomic Energy Commission, Directorate of Licensin

Dockets: 05000286 50-286 Indian Point Station, Unit 3, Power Authority of Stat

File Locations: PDR ADOCK 05000286 A

740412 Package: 8111120605 #

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

==== TCON59 ===== Accession Number - 8203230754 ===== Start ===== End ==

Availability: PDR Format: *

Microfilm Address: 12385-293 12385-294

Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 810312
Desc/: LER 82-023/03L-0:on 820212,PT-39B.2 & PT-39B.1 revealed that snubbers
Title: 1-RC-HSS-131,1-WFPD-HSS-15 & 1-SHP-HSS-35B were inoperable due to low
: oil reservoir level.Caused by seal leakage.Snubbers replaced &/or
: repaired.

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region 2 (RII, Post 820201)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 82-023

820212

Event Date

File Locations: PDR ADOCK 05000280 S

820312 Package: 8203230738 C

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDUCS/HD>> Nuclear Regulatory Commission HDQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8210290276 ===== Start ===== End ===
Availability: PDR Format: * Microfilm Address: 15853-131 15853-132
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 821022
Desc/: LER 82-102/03L-0:on 820923,discovered pin attaching snubber
Title: 1-SHP-HSS-35B to main steam line partially out & snubber cocked.Caused
: undetermined.Snubber straightened & pins properly installed.

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region 2 (RII, Post 820201)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 82-102 820923 Event Date

File Locations: PDR ADOCK 05000280 S 821022 Package: 8210290264 B

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8211220317 ===== Start ===== End =====
Availability: PDR Format: * Microfilm Address: 16165-154 16165-156
Size: 3pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 821108
Desc/: LER 82-101/03L-0:on 821009,snubbers 1-SHP-HSS-35B,
Title: 1-SW-MSS-2,1-S1-HSS-100,1-WFPD-HSS-14,WFPD-HSS-15 & 1-RC-HSS-116 found
: inoperable.Caused by fitting leaks & failure to stroke due to
: corrosion.Snubbers replaced.

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region 2 (RII, Post 820201)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt #	82-101	821009	Event Date
----------------------	--------	--------	------------

File Locations: PDR ADOCK 05000280 S 821108 Package: 8211220314 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8211230461 ===== Start ===== End ===
Availability: PDR Format: * Microfilm Address: 16192-085 16192-086
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 821115
Desc/: LER 82-118/03L-0:on 821015,reservoir tubing for snubber 1-SHP-HSS-34A
Title: found cut.Caused by personnel error during removal of snubber
: reservoirs & unused tubing.Tubing repaired.
:

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region 2 (RII, Post 820201)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 82-118 821015 Event Date

File Locations: PDR ADOCK 05000280 S 821115 Package: 8211230444 B

There Is Not A Text Or Abstract File Available For Viewing.

Count: *0

<Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission HDQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8305100129 ===== Start ===== End =====
Availability: PDR Format: * Microfilm Address: 18375-046 18375-047
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 830503
Desc/: LER 83-019/03L-0:on 830408,performance of Periodic Test 1-PT-39B-2
Title: revealed snubbers 1-WFPD-HSS-15,1-RC-HSS-115, 1-SI-HSS-27A,1-RH-HSS-12
: & 1-SI-HSS-28 inoperable.Caused by fluid leaks & loose pipe
: clamp.Snubbers replaced.
Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region 2 (RII, Post 820201)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 83-019 830408 Event Date

File Locations: PDR ADOCK 05000280 S 830503 Package: 8305100115 B

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOLCS/AD>>

Nuclear Regulatory Commission

ADQ42 V6.3.23.0

==== TCON59 ===== Accession Number - 8505130243 ===== Start ==== End ===

Availability: PDR Format: * Microfilm Address: 30379-313 30379-314

Size: 2pp.

Document Type: Outgoing correspondence

Issued: 850429

Desc/: Forwards Amend 22, renewing License 29-01675-01.

Title:

:
:
:

Authors: GLENN, J.E.

Region 1 (RI, Post 820201)

Recipients: PALAZZO, W.L.

Palazzo, W. L. MD

Dockets: 03002440

Internal Tracking # 02497

License Number 29-01675-01

File Locations: REG1 LIC30 *

29-01675-01

850429 Package: 8505130240 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOCS/HD>>

Nuclear Regulatory Commission

ADQ42 V6.3.23.0

==== TCON59 ===== Accession Number - 8311010400 ===== Start ===== End =====

Availability: PDR Format: *

Microfilm Address: 20973-328 20973-331

Size: 4pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 831020
Desc/: LER 83-044/03L-0:on 830920,Periodic Test PT-39B-1 revealed snubber
Title: 1-SHP-HSS-1B inoperable & 1-PT-39B-2 revealed snubbers
: 1-RC-HSS-146-147 inoperable.Caused by snubber binding on pipe & empty
: fluid reservoir.W/831020 ltr.
Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: O'REILLY,J.P. Region 2 (RII, Post 820201)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 83-044
Other Related Number 83-074

830920 Event Date

File Locations: PDR ADOCK 05000280 S

831020 Package: 8311010400 #

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit:

Count: *0

<Replace>

<<NUDOCS/AD>>

Nuclear Regulatory Commission

ADQ42 V6.3.23.0

==== TCON59 ===== Accession Number - 8404230001 ===== Start ===== End =====

Availability: PDR Format: TXT

Microfilm Address: 24153-061 24153-062

Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 840418
Desc/: LER 84-011-00:on 840329,turbine bldg ventilation radiation monitors A
Title: & B failed simultaneously,downscale,resulting in ventilation
: isolation.Caused by moisture entering cable connectors to
: monitors.W/840418 ltr.

Authors: LINDSEY,D.J. Power Authority of the State of New York (New York P

MCNEILL,C.A. Power Authority of the State of New York (New York P

Recipients: * Records Services Branch (Document Control Branch)

Dockets: 05000333 50-333 James A. FitzPatrick Nuclear Power Plant, Power Autho

Licensee Event Rpt # 84-011

840329

Event Date

Other Related Number JAFP-84-0418

File Locations: PDR ADOCK 05000333 S

840418 Package: 8404230001 #

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOCS/AD>>

Nuclear Regulatory Commission

ADQ42 V6.3.23.0

==== TCON59 ===== Accession Number - 9205220071 ===== Start ==== End ===

Availability: PDR Format: TXT

Microfilm Address: 61791-313 61791-317

Size: 5pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 920515
Desc/: LER 92-006-00:on 920424,determined that three snubbers did not satisfy
Title: one acceptance criteria of TS 4.17.E.1a. Caused by personnel error.No
: immediate action necessary. W/920515 ltr.

Authors: KANSLER,M.R. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Document Control Branch (Document Control Desk) (

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 92-006

920424

Event Date

Other Related Number 92-344

File Locations: PDR ADOCK 05000280 S

920515 Package: 9205220071 #

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDUCS/HD>>

Nuclear Regulatory Commission

HDQ42 V6.3.23.0

==== TCON59 ===== Accession Number - 9901270157 ===== Start ===== End ==

Availability: PDR Format: TXT

Microfilm Address: A6663-094 A6663-096

Size: 3pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 990121
Desc/: LER 99-001-00:on 981222,auxiliary feedwater pipe support missed
Title: surveillance.Caused by personnel error.Station deviation rept was
: submitted.Two supports in question received required Code insp & were
: found acceptable.

Authors: GRECHECK,E.S. Virginia Power (Virginia Electric & Power Co.)

Recipients:

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 99-001

981222

Event Date

File Locations: PDR ADOCK 05000280 S

990121 Package: 9901270151 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOLCS/HD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8110290476 ===== Start ==== End ====
Availability: PDR Format: * Microfilm Address: 10387-012 10387-013
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 811019
Desc/: LER 81-055/03L-0:on 810925,snubber 1-WGCB-HSS-03 on B steam generator
Title: blowout line was not inspected during PT-39A-2. Caused by inadvertent
: omission from updated periodic test data sheet.Snubber inspected &
: added to sheet.

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region 2, Ofc of the Director (810301-820201)

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe

Licensee Event Rpt # 81-055 810925 Event Date

File Locations: PDR ADOCK 05000280 S 811019 Package: 8110290466 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDUCS/HD>>

Nuclear Regulatory Commission

ADQ42 V6.3.23.0

==== TCON59 ===== Accession Number - 7903130353 ===== Start ==== End ===

Availability: PDR Format: * Microfilm Address: 15078-016 15078-017

Size: 2pp.

Document Type: Licensee Event Report (See also AO,R0) Issued: 790307
Desc/: LER 79-009/03L-0 on 790208:while performing penetrant test
Title: 39B-1,mechanic discovered 3 snubbers were not on test.Caused by
: inadvertent omission.Change initiated to add 3 snubbers to penetrant
: test 39B-1.

Authors: STEWART,W.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

Licensee Event Rpt # 79-009

File Locations: PDR ADOCK 05000281 S

790308 Package: 7903130348 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission HDQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 7904090195 ===== Start ===== End =====
Availability: PDR Format: * Microfilm Address: 15078-013 15078-014
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 790403
Desc/: LER 79-010/03L-0 on 790306:during tests,19 of 30 snubbers did not meet
Title: acceptance criteria.Caused by setting drift & non-readjustment to
: optimum settings after previous satisfactory tests.Snubbers
: readjusted,repaired or replaced.
Authors: STEWART,W.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe
Licensee Event Rpt # 79-010

File Locations: PDR ADOCK 05000281 S 790404 Package: 7904090192 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

==== TCON59 ===== Accession Number - 7911300547 ===== Start ===== End ===

Availability: PDR Format: *

Microfilm Address: 01439-358 01439-359

Size: 2pp.

Document Type: Incoming Correspondence

Issued: 791128

Desc/: Discusses seismic analyses of piping sys & methods used to conform to

Title: NRC requirements. LER will be issued re significant items that impact
: sys operability. No notification required for other conditions.
:

Authors: SPENCER, W.C. Virginia Power (Virginia Electric & Power Co.)

Recipients: DENTON, H.R. Office of Nuclear Reactor Regulation, Director

Dockets: 05000280 50-280 Surry Power Station, Unit 1, Virginia Electric & Powe
05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

File Locations: PDR ADOCK 05000280 P

791128 Package: 7911300547 #

PDR ADOCK 05000281 P

791128

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8009020090 ===== Start ==== End ===
Availability: PDR Format: * Microfilm Address: 06452-277 06452-279
Size: 3pp.

Document Type: Licensee Event Report (See also R0,R0) Issued: 800825
Desc/: Updated LER 79-008/03X-1:on 790209,during surveillance check,found
Title: deterioration of piping on low portion of recirculation spray
: subsystems.Caused by chloride stress corrosion.Piping replaced
: w/nonsensitized piping.
Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

Licensee Event Rpt #	79-008	790209	Event Date
----------------------	--------	--------	------------

File Locations: PDR ADOCK 05000281 S 800825 Package: 8009020088 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8009220309 ===== Start ==== End ===
Availability: PDR Format: * Microfilm Address: 06593-278 06593-279
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 800912
Desc/: LER 80-012/03L-0:on 800815,review of Unit 2 pipe support showed that
Title: seismic support for charging pump 2-CH-P-1B had not been
: installed.Caused by administrative error.Support installed.

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

Licensee Event Rpt # 80-012 800815 Event Date

File Locations: PDR ADOCK 05000281 S 800912 Package: 8009220248 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8011180609 ===== Start ===== End =====
Availability: PDR Format: * Microfilm Address: 06988-112 06988-113
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 801113
Desc/: LER 80-031/03L-0:on 801015,pipe support in alternate charging header
Title: found in overstressed condition per IE Bulletin 79-14,Suppl 2.Caused
: by faulty installation. Modified support & returned subsys to svc.

Authors: * Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

Internal Tracking # IEB-79-14 801015 Event Date
Licensee Event Rpt # 80-031

File Locations: PDR ADOCK 05000281 S 801113 Package: 8011180601 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/AD>>

Nuclear Regulatory Commission

ADQ42 V6.3.23.0

==== TCON59 ===== Accession Number - 8012170636 ===== Start ==== End ===

Availability: PDR Format: * Microfilm Address: 07264-180 07264-181

Size: 2pp.

Document Type: Licensee Event Report (See also AO,R0) Issued: 801211
Desc/: LER 80-041/03L-0:on 801112,snubber 2-WFPD-HSS-18 found to have bent
Title: rod-eye & was declared inoperable.Caused by improper alignment of pipe
: clamp to snubber.Snubber replaced.

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region II, RII (IE, 720101-810228)

Dockets: 05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

Licensee Event Rpt # 80-041 801112 Event Date

File Locations: PDR ADOCK 05000281 S 801211 Package: 8012170611 B

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

==== TCON59 ===== Accession Number - 8105200297 ===== Start ==== End ===
Availability: PDR Format: * Microfilm Address: 08573-137 08573-138
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 810515
Desc/: LER 81-023/03L-0:on 810422,PT-39B-2 indicated snubbers to be
Title: inoperable per Tech Spec 4.17.Caused by leakage around valve block or
: through connections at reservoir. Inoperable snubbers replaced.

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region 2, Ofc of the Director (810301-820201)

Dockets: 05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

Licensee Event Rpt # 81-023 810422 Event Date

File Locations: PDR ADOCK 05000280 S 810515 Package: 8105200295 B
PDR ADOCK 05000281 S 810515

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOLCS/HD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8111050758 ===== Start ===== End ===
Availability: PDR Format: * Microfilm Address: 10487-308 10487-309
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 811026
Desc/: LER 81-066/03L-0:on 811003,snubbers 1-CC-HSS-356A & B discovered w/no
Title: fluid level in reservoirs.Caused by leak at mechanical connection on
: reservoirs.Snubber units replaced.
:

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region 2, Ofc of the Director (810301-820201)

Dockets: 05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

Licensee Event Rpt # 81-066 811003 Event Date

File Locations: PDR ADOCK 05000280 S 811026 Package: 8111050742 B
PDR ADOCK 05000281 S 811026

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8206010585 ===== Start ===== End ===
Availability: PDR Format: * Microfilm Address: 13314-118 13314-119
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 820402
Desc/: LER 82-016/03L-0:on 820303,snubber 2-S1-HSS-20 found inoperable due to
Title: low oil reservoir level.Caused by seal leakage.Snubber repaired,tested
: & reinstalled.
:

Authors: * Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region 2 (RII, Post 820201)

Dockets: 05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

Licensee Event Rpt #	82-016	820303	Event Date
----------------------	--------	--------	------------

File Locations: PDR	ADOCK 05000280 S	820402 Package: 8206010574 A
PDR	ADOCK 05000281 S	820402

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8208120175 ===== Start ===== End ===
Availability: PDR Format: * Microfilm Address: 14319-153 14319-154
Size: 2pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 820802
Desc/: LER 82-042/03L-0:on 820706,main steam line snubber found w/ oil in
Title: reservoir.Caused by leaking rod seal due to improper
: installation.Spare snubber tested & installed.
:

Authors: WILSON,J.L. / Virginia Power (Virginia Electric & Power Co.)

Recipients: * Region 2 (RII, Post 820201)

Dockets: 05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

Licensee Event Rpt # 82-042 820706 Event Date

File Locations: PDR ADOCK 05000280 S 820802 Package: 8208120166 B
PDR ADOCK 05000281 S 820802

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>

<<NUDOLCS/HD>>

Nuclear Regulatory Commission

HDQ42 V6.3.23.0

==== TCON59 ===== Accession Number - 8910260248 ===== Start ==== End ===

Availability: PDR Format: TXT

Microfilm Address: 51611-310 51611-313

Size: 4pp.

Document Type: Licensee Event Report (See also AO,R0) Issued: 891018
Desc/: LER 89-011-00:on 890919,found that pipe support rigidly attached to
Title: auxiliary bldg structure & facility containment which violates design
: requirements.Caused by design error. Pipe support modified.W/891018
: ltr.

Authors: KANSLER,M.R. Virginia Power (Virginia Electric & Power Co.)

Recipients: * Document Control Branch (Document Control Desk) (

Dockets: 05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

Internal Tracking # IEB-79-02

890919

Event Date

Internal Tracking # IEB-79-14

File Locations: PDR ADOCK 05000281 S

891018 Package: 8910260248 #

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOCS/AD>>

Nuclear Regulatory Commission

ADQ42 V6.3.23.0

==== TCON59 ===== Accession Number - 8404270035 ===== Start ==== End ==

Availability: PDR Format: TXT

Microfilm Address: 24218-069 24218-079

Size: 11pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 840423
Desc/: LER 84-004-00:on 840315,67 of 267 snubbers failed to meet acceptance
Title: criteria stipulated in snubber administrative procedures.Snubber
: program being revised to provide better controls on maint & tracking
: of snubbers.

Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients:

Dockets: 05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

Licensee Event Rpt # 84-004

840315

Event Date

File Locations: PDR ADOCK 05000281 S

840423 Package: 8404270031 A

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.

Count: *0

<Replace>

<<NUDOCS/AD>> Nuclear Regulatory Commission ADQ42 V6.3.23.0
==== TCON59 ===== Accession Number - 8309190245 ===== Start ==== End ===
Availability: PDR Format: * Microfilm Address: 20413-284 20413-287
Size: 4pp.

Document Type: Licensee Event Report (See also A0,R0) Issued: 830912
Desc/: LER 83-034/03L-0:on 830813,w/unit at constant speed drive, periodic
Title: snubber functional testing revealed 23 snubbers failed to meet
: required acceptance criteria.Caused by seal degradation & scored
: piston/body.W/830912 ltr.
Authors: WILSON,J.L. Virginia Power (Virginia Electric & Power Co.)

Recipients: O'REILLY,J.P. Region 2 (RII, Post 820201)

Dockets: 05000281 50-281 Surry Power Station, Unit 2, Virginia Electric & Powe

Licensee Event Rpt #	830813	Event Date
83-034		
Other Related Number 83-063		

File Locations: PDR ADOCK 05000281 S 830912 Package: 8309190245 #

Use HOME/TAB To View Additional Information, ENTER To View Text, ESCape To Exit.
Count: *0 <Replace>