



Entergy Operations, Inc.
River Bend Station
5485 U.S. Highway 61
P. O. Box 220
St. Francisville, LA 70775
Tel 225 336 6225
Fax 225 635 5068

Rick J. King
Director
Nuclear Safety Assurance

December 15, 1999

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Subject: River Bend Station
Docket No. 50-458
Monthly Operating Report

File No.: G9.5, G4.25

RBG-45199
RBF1-99-0335

Ladies and Gentlemen:

In accordance with River Bend Station Technical Specification 5.6.4, enclosed is the Monthly Operating Report for November 1999.

Sincerely,

A handwritten signature in cursive script that reads "Rick J. King".

RJK/dhw
enclosure

Handwritten initials, possibly "JLK", in a stylized cursive font.

PO2 APOCK 03000458

Monthly Operating Report
December 15, 1999
RBG-45199
RBF1-99-0335
Page 2 of 2

cc: U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

NRC Senior Resident Inspector
P. O. Box 1050
St. Francisville, LA 70775

INPO Records Center
700 Galleria Parkway
Atlanta, GA 30339-3064

Mr. Jim Calloway
Public Utility Commission of Texas
1701 N. Congress Ave.
Austin, TX 78711-3326

Dottie Sherman
American Nuclear Insurers
29 South Main Street
West Hartford, CT 06107

DOCKET NO. 50/458

RIVER BEND STATION

DATE December 15, 1999

COMPLETED BY Danny H. Williamson

TITLE Sr. Licensing Specialist

TELEPHONE 225-381-4279

PAGE 1 OF 2

OPERATING STATUS

1. REPORTING PERIOD: November 1999
2. MAXIMUM DEPENDABLE CAPACITY (MWe-Net): 936
3. DESIGN ELECTRICAL RATING (MWe-Net): 936

	<u>MONTH</u>	<u>YEAR TO DATE</u>	<u>CUMULATIVE</u>
4. NUMBER OF HOURS REACTOR WAS CRITICAL	<u>716.9</u>	<u>5845.2</u>	<u>94555.6</u>
5. HOURS GENERATOR ON LINE	<u>683.0</u>	<u>5733.2</u>	<u>91103.4</u>
6. UNIT RESERVE SHUTDOWN HOURS	<u>0</u>	<u>0</u>	<u>0</u>
7. NET ELECTRICAL ENERGY GENERATED (MWH)	<u>625,013</u>	<u>4,996,960</u>	<u>79,720,275</u>

UNIT SHUTDOWNS


<u>NUMBER</u>	<u>DATE</u>	<u>TYPE</u>	<u>DURATION</u>	<u>SHUTDOWN METHOD</u>	<u>REASON</u>	<u>CAUSE / CORRECTIVE ACTIONS</u>
99-03	991029	F	37 hr.	3	H	During installation of communications equipment at plant substation, improper use of test equipment caused a trip signal to the main generator output breakers, which resulted in a main turbine trip and reactor scram. This event was reported in Licensee Event Report 50-458/99-014-00.

LEGEND:

TYPE:	F - Forced S - Scheduled	SHUTDOWN METHOD:	1 - Manual 2 - Manual trip/scram 3 - Automatic trip/scram 4 - Continuation 5 - Other (explain)	REASON:	A - Equipment failure (explain) B - Maintenance or Test C - Refueling D - Regulatory restriction E - Operator training / License exam F - Administrative G - Operational error (explain) H - Other (explain)
--------------	-----------------------------	-------------------------	--	----------------	---

NOTES:

1. No challenges to the reactor safety-relief valves occurred in November.



 Danny H. Williamson