

Robinson 2

3Q/2006 Plant Inspection Findings

Initiating Events

Mitigating Systems

Significance:  Mar 31, 2006

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Demonstrate Performance of Safety-Related Breaker Effectively Controlled

The inspectors identified a non-cited violation of 10 CFR 50.65(a)(2) for failure to demonstrate that the performance of a safety-related breaker was being effectively controlled through the performance of appropriate preventive maintenance, in that repetitive failures that caused a performance criteria to be exceeded were not identified and, as a result goal setting and monitoring was not conducted as required by 10 CFR 50.65(a)(1).

The finding is greater than minor because it is associated with the equipment performance attribute of the Mitigating Systems Cornerstone and affects the cornerstone objective of ensuring the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences (i.e., core damage). The failure to identify and properly account for repetitive failures of a safety-related valve breaker resulted in goal setting and monitoring not being performed between the period of October 2005 and March 2006. This finding was of very low safety significance because it is not a design or qualification deficiency, does not represent an actual loss of safety function for a system or train, and is not risk significant due to a seismic, fire, flooding, or severe weather initiating event.. The cause of this finding is inattention to detail during validation and verification of assumptions made during the MR evaluations, and is therefore, identified as a performance aspect of the Human Performance cross-cutting area. (Section 1R12)

Inspection Report# : [2006002\(pdf\)](#)

Barrier Integrity

Emergency Preparedness

Occupational Radiation Safety

Significance:  Jun 30, 2006

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Meet Technical Specification Requirements for Radiation Protection Manager Qualification

The inspectors identified a non-cited violation (NCV) of Technical Specifications (TS) 5.3.1 for failure to ensure the Manager of Radiation Control function met the minimum qualification requirements specified in ANSI/ANS 3.1-1981,

American National Standard for Selection, Qualification, and Training of Personnel for Nuclear Power Plants.

The finding is greater than minor because it is associated with the Occupational Radiation Safety Cornerstone attribute of Program and Process and adversely affected the cornerstone objective of ensuring the adequate protection of the worker health and safety from exposure to radiation from radioactive material during routine civilian nuclear reactor operation. This finding was evaluated using the Occupational Radiation Safety SDP and was determined to be of very low safety significance because there were supervisors in the Radiation Protection department who met the minimum qualification requirements for this position and these individuals provided advise and assistance to the assigned Manager of Radiation Control. This finding was entered into the corrective action program as Action Requests (ARs) 187587 and 196260 (Section 2OS1).

Inspection Report# : [2006003\(pdf\)](#)

Public Radiation Safety

Physical Protection

[Physical Protection](#) information not publicly available.

Miscellaneous

Last modified : December 21, 2006