



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-4005

August 30, 2005

Gregg R. Overbeck, Senior Vice
President, Nuclear
Arizona Public Service Company
P.O. Box 52034
Phoenix, AZ 85072-2034

SUBJECT: MIDCYCLE PERFORMANCE REVIEW AND INSPECTION PLAN -
PALO VERDE NUCLEAR GENERATING STATION

Dear Mr. Overbeck:

On August 3, 2005, the NRC staff completed its performance review of Palo Verde for the first half of the calendar year 2005 assessment cycle. Our technical staff reviewed performance indicators (PIs) for the most recent quarter and inspection results over the previous 12 months. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility in order for you to inform us of any planned inspections that may conflict with your plant activities.

This performance review and enclosed inspection plan do not include physical protection information. A separate letter designated and marked as "Proprietary Information in accordance with 10 CFR 2.390" will include the physical protection review and resultant inspection plan.

Plant performance for the most recent quarter for all three units was within the Degraded Cornerstone column of the NRC's Action Matrix based on a Yellow inspection finding in the Mitigating Systems cornerstone. The issue involved your discovery in July 2004, following notification from another facility where a similar problem had been identified, that a significant section of containment sump safety injection piping at all three units was void of water. The voided section of piping had the potential to prevent the fulfillment of the safety function to remove residual heat and mitigate the consequences of a loss-of-coolant accident. In response to this finding you initiated a number of investigative teams to identify the root and contributing causes of the finding and to develop corrective actions to preclude repetition. The root cause analyses were ongoing at the end of this assessment period.

On June 14, 2005, Arizona Public Service Company (APS) submitted a letter to the NRC requesting postponement of the planned NRC supplemental inspection (Inspection Procedure 95002, "Inspection for One Degraded Cornerstone or Any Three White Inputs In a Strategic Performance Area") in order to allow sufficient time to complete the root cause evaluations and develop corrective actions. Accordingly, the NRC staff will conduct the inspection in September 2005. While we agree with the basis for your request, you should recognize that the postponement of the closure of this issue and our inspection will result in the Yellow finding remaining open for a least five quarters.

In our annual assessment letter dated March 2, 2005, we advised you of a substantive crosscutting issue in the area of human performance. This substantive crosscutting issue primarily involved personnel errors (e.g., failure to follow procedures) and resource issues (e.g., inadequate procedures). During the current 12-month assessment cycle there were 18 findings of very low safety significance (Green) with human performance attributes in the Initiating Events, Mitigating Systems, Barrier Integrity, Emergency Preparedness, and Public Radiation Safety Cornerstones. The findings have the same common themes as those described in the annual assessment letter. Recent noteworthy examples included the failure of personnel to follow procedures during the operation of fuel handling equipment, an inadequate surveillance procedure which resulted in an inadvertent safety injection actuation and injection, and inadequate procedures for the operation of multiple charging pumps and a makeup pump from the refueling water storage tank. Additionally, the NRC staff identified a new causal factor involving organizational issues (e.g., communications between departments). Noteworthy examples included the inappropriate sequencing of work that resulted in a loss of vital power to one train of the engineered safety features system and the failure to promptly notify the control room of a condition that impacted the operability of the emergency core cooling system.

In our March 2, 2005, annual assessment letter we also advised you of a substantive crosscutting issue in the area of problem identification and resolution. This substantive crosscutting issue involved implementation problems associated with identifying problems and entering them in the corrective action program, evaluating conditions in the corrective action program, and implementing effective corrective actions. During the current 12-month assessment cycle there were 20 findings of very low safety significance (Green) with problem identification and resolution attributes in the Initiating Events, Mitigating Systems, and Barrier Integrity Cornerstones. These findings have the same common themes as those described in the annual assessment letter. Recent noteworthy examples included the failure to implement corrective actions to preclude the failure of gasket retaining bolts on emergency core cooling system valves, the failure of personnel to suspend spent fuel movements upon discovery of a degraded condition, and the failure to revise procedures to ensure auxiliary feedwater check valves were appropriately tested.

Your staff initiated several reviews to determine the root cause analyses of the underlying performance deficiencies and to develop corrective actions to improve performance in these substantive crosscutting areas. The root cause analyses were ongoing at the end of the assessment period. We noted that, while you have implemented some corrective actions to improve performance, these activities were not fully effective in developing a continuing performance improvement trend. Therefore, both substantive crosscutting areas will remain open. We will continue to monitor your actions to address the crosscutting areas through implementation of the resident inspector baseline inspection program and during the January 2006 biannual problem identification and resolution inspection. The closure of these issues will be based on the thoroughness of your root cause evaluations and whether your corrective actions are successful in improving performance within the specific areas previously discussed.

The March 2, 2005, annual assessment letter discussed aspects of your actions to enhance the safety conscious work environment at Palo Verde. Additionally, the results of a Palo Verde employee survey completed in March 2005 were discussed with the NRC during public

meetings conducted on April 5, 2005, and August 18, 2005. The results of the survey indicated that, with some exceptions, there has been improvement in the work environment and employee willingness to raise safety issues. As discussed during the August 18, 2005, meeting, there were some conflicting elements within the survey results (e.g., statistical results of survey questions relative to write-in comments) and the results indicate some pockets of potential issues needing further action on your part. We understand the steps you are planning to take to address these and will continue to conduct focused reviews of your activities within this area as part of our implementation of the baseline inspection program.

On April 8, 2005, the staff issued a Severity Level III violation and proposed imposition of a \$50,000 civil penalty in accordance with the NRC's Enforcement Policy. The violation involved the NRC's identification of a failure to perform a 10 CFR 50.59 safety evaluation and receive prior NRC approval of a change to Procedure 41ST-1SI09, "ECCS (emergency core cooling system) Leak Test." This change resulted in the draining of ECCS suction piping from the containment sump following local leak rate testing. If an evaluation had been performed in 1992, then it would have led to a conclusion that the change was contrary to the description of the facility in the Updated Final Safety Analysis Report and that such a change would have required NRC review and approval prior to implementation. In response to this finding, you initiated several investigative teams to identify the root and contributing causes of the finding and to develop corrective actions to preclude repetition. The root cause analyses were ongoing at the end of the assessment period. The NRC staff will conduct an inspection of your root cause analyses and corrective actions during the September 2005 planned supplemental inspection.

On June 27, 2005, the staff issued a Severity Level III violation in accordance with the NRC's Enforcement Policy. The violation involved the NRC's identification of a change to the Palo Verde Emergency Plan without prior Commission approval, which decreased the plan's effectiveness. The change involved the removal of a classifiable condition from two emergency action level (EAL) definitions, which made the EALs technically inaccurate and unable to be implemented as written. In response to the finding, APS made revisions to the Emergency Plan to correct the discrepancies, added staffing to the emergency planning department to ensure appropriate reviews of changes to the Emergency Plan were conducted, and completed a review of the change process for the Security Plan, Quality Assurance Program, and Fire Protection plans. The NRC staff will conduct an inspection of your root cause analyses and corrective actions prior to the annual assessment review in February 2006.

The enclosed inspection plan details the inspections, except those related to physical protection, scheduled through March 31, 2007. In addition to the baseline inspections, NRC will also be implementing Inspection Procedure 50001, "Steam Generator Replacement Inspection," relative to the planned replacement of the Unit 1 steam generators. The inspection plan is provided to minimize the resource impact on your staff and to allow for the early resolution of any scheduling conflicts and personnel availability issues well in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last 9 months of the inspection plan are tentative and may be revised at the end-of-cycle meeting.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public

Document Room or from the Publically Available Records (PARS) component of the NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (The Public Electronic Reading Room).

If circumstances arise which cause us to change the inspection plan, we will contact you to discuss the change as soon as possible. Please contact Troy W. Pruett at (817) 860-8173 with any questions you may have regarding this letter or the inspection plan.

Sincerely,



Bruce S. Mallett
Regional Administrator

Dockets: 50-528
50-529
50-530
Licenses: NPF-41
NPF-51
NPF-74

Enclosure:
Palo Verde Inspection/Activity Plan

cc w/enclosure:

Steve Olea
Arizona Corporation Commission
1200 W. Washington Street
Phoenix, AZ 85007

Douglas K. Porter, Senior Counsel
Southern California Edison Company
Law Department, Generation Resources
P.O. Box 800
Rosemead, CA 91770

Chairman
Maricopa County Board of Supervisors
301 W. Jefferson, 10th Floor
Phoenix, AZ 85003

Aubrey V. Godwin, Director
Arizona Radiation Regulatory Agency
4814 South 40 Street
Phoenix, AZ 85040

Craig K. Seaman, Director
Regulatory Affairs
Palo Verde Nuclear Generating Station
Mail Station 7636
P.O. Box 52034
Phoenix, AZ 85072-2034

Hector R. Puente
Vice President, Power Generation
El Paso Electric Company
310 E. Palm Lane, Suite 310
Phoenix, AZ 85004

Jeffrey T. Weikert
Assistant General Counsel
El Paso Electric Company
Mail Location 167
123 W. Mills
El Paso, TX 79901

John W. Schumann
Los Angeles Department of Water & Power
Southern California Public Power Authority
P.O. Box 51111, Room 1255-C
Los Angeles, CA 90051-0100

John Taylor
Public Service Company of New Mexico
2401 Aztec NE, MS Z110
Albuquerque, NM 87107-4224

Thomas D. Champ
Southern California Edison Company
5000 Pacific Coast Hwy, Bldg. D1B
San Clemente, CA 92672

Robert Henry
Salt River Project
6504 East Thomas Road
Scottsdale, AZ 85251

Brian Almon
Public Utility Commission
William B. Travis Building
P.O. Box 13326
1701 North Congress Avenue
Austin, TX 78701-3326

Karen O'Regan
Environmental Program Manager
City of Phoenix
Office of Environmental Programs
200 West Washington Street
Phoenix, AZ 85003

Institute of Nuclear Power Operations (INPO)
Records Center
700 Galleria Parkway SE, Suite 100
Atlanta, GA 30339

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates Start	Planned Dates End	Inspection Type
1, 2, 3	OB-RQ - PV REQUALIFICATION INSP		3			
	IP 7111111B	Licensed Operator Requalification Program		08/07/2006	08/11/2006	Baseline Inspections
1, 2, 3	PEB-05T - TRIENNIAL FIRE PROTECTION		3			
	IP 7111105T	Fire Protection [Triennial]		09/11/2006	09/15/2006	Baseline Inspections
1, 2, 3	IP 7111105T	Fire Protection [Triennial]		09/25/2006	09/29/2006	Baseline Inspections
2	EB08 - ISI-P		1			
	IP 7111108P	Inservice Inspection Activities - PWR		10/02/2006	11/03/2006	Baseline Inspections
1, 2, 3	ALARA2 - ALARA PLANNING AND CONTROLS		1			
	IP 7112102	ALARA Planning and Controls		01/08/2007	01/12/2007	Baseline Inspections
1, 2	12B - MAINTENANCE RULE INSPECTION		2			
	IP 7111112B	Maintenance Effectiveness		01/22/2007	01/26/2007	Baseline Inspections
1, 2, 3	RP TEAM - RADIATION SAFETY TEAM		5			
	IP 7112103	Radiation Monitoring Instrumentation and Protective Equipment		01/29/2007	02/02/2007	Baseline Inspections
1, 2, 3	IP 7112201	Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems		01/29/2007	02/02/2007	Baseline Inspections
1, 2, 3	IP 7112202	Radioactive Material Processing and Transportation		01/29/2007	02/02/2007	Baseline Inspections
1, 2, 3	IP 7112203	Radiological Environmental Monitoring Program (REMP) And Radioactive Material Control F		01/29/2007	02/02/2007	Baseline Inspections
1, 2, 3	EP1 - PV EP EXERCISE		3			
	IP 7111401	Exercise Evaluation		03/05/2007	03/09/2007	Baseline Inspections
1, 2, 3	EB02/21 - 50.59 & PERMANENT PLANT MODS		3			
	IP 7111102	Evaluation of Changes, Tests, or Experiments		03/12/2007	03/16/2007	Baseline Inspections
1, 2, 3	IP 7111117B	Permanent Plant Modifications		03/12/2007	03/16/2007	Baseline Inspections
1, 2, 3	ACRSA - ACCESS CONTROL TO RAD AREAS		1			
	IP 7112101	Access Control to Radiologically Significant Areas		04/09/2007	04/09/2007	Baseline Inspections

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates Start	Planned Dates End	Inspection Type
1	SG REPL - U1 STEAM GEN REPLACEMENT		4			
	IP 50001	Steam Generator Replacement Inspection		02/28/2005	12/31/2005	Other Routine
1, 2, 3	SUP INSP - 95002 SUPPLEMENTAL INSP		6			
	IP 95002	Inspection For One Degraded Cornerstone Or Any Three White Inputs In A Strategic Perform		09/12/2005	09/16/2005	Supplemental Progra
1, 2, 3	IP 95002	Inspection For One Degraded Cornerstone Or Any Three White Inputs In A Strategic Perform		09/26/2005	09/30/2005	Supplemental P Progra
1	OB-INIT - INITIAL EXAM		3			
	X02282	PALO VERDE UNIT1 (05/05) INITIAL EXAM		08/01/2005	08/05/2005	Not Applicable
2	X02283	PALO VERDE UNIT 2 (11/05) - INITIAL EXAM		08/01/2005	08/05/2005	Not Applicable
3	X02284	PALO VERDE UNIT 3 (11/05) - INITIAL EXAM		08/01/2005	08/05/2005	Not Applicable
1	EB08P - ISI U1 - VESS VOL (TI 150/152) AS REQ		2			
	IP 7111108P	Inservice Inspection Activities - PWR		10/18/2005	10/27/2005	Baseline Inspections
1	IP 2515/160	Pzr Pene Nozzles & Strm Space Piping Connections in U.S. PWRs [NRC Bulletin 2004-01]		11/14/2005	12/02/2005	Safety Issues
1, 2, 3	ACRSA - ACCESS CONTROL TO RAD SIGNIFICANT AREAS		1			
	IP 7112101	Access Control to Radiologically Significant Areas		10/17/2005	10/21/2005	Baseline Inspections
1, 2, 3	711152B - PV PIR INSPECTION		7			
	IP 711152B	Identification and Resolution of Problems		01/09/2006	01/13/2006	Baseline Inspections
1, 2, 3	IP 71152B	Identification and Resolution of Problems		01/23/2006	01/27/2006	Baseline Inspections
1, 2, 3	OB-EP2 - EMERG PREPAREDNESS PROGRAM INSPECTION		1			
	IP 7111402	Alert and Notification System Testing		01/23/2006	01/27/2006	Baseline Inspections
1, 2, 3	IP 7111403	Emergency Response Organization Augmentation Testing		01/23/2006	01/27/2006	Baseline Inspections
1, 2, 3	IP 7111404	Emergency Action Level and Emergency Plan Changes		01/23/2006	01/27/2006	Baseline Inspections
1, 2, 3	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies		01/23/2006	01/27/2006	Baseline Inspections
1, 2, 3	IP 711151	Performance Indicator Verification		01/23/2006	01/27/2006	Baseline Inspections
1, 2, 3	ALARA1 - ALARA PLANNING AND CONTROLS		1			
	IP 7112102	ALARA Planning and Controls		02/13/2006	02/17/2006	Baseline Inspections
2	EB08 - U3-ISI		1			
	IP 7111108P	Inservice Inspection Activities - PWR		04/03/2006	05/05/2006	Baseline Inspections
1, 2, 3	ACRSA - ACCESS CONTROL TO RAD SIGNIFICANT AREAS		1			
	IP 7112101	Access Control to Radiologically Significant Areas		04/10/2006	04/14/2006	Baseline Inspections
1, 2, 3	PEB - HX PERFORMANCE		1			
	IP 7111107B	Heat Sink Performance		06/05/2006	06/09/2006	Baseline Inspections
1, 2, 3	EB21 - ENG-SSD&PC		5			
	IP 7111121	Safety System Design and Performance Capability		07/31/2006	08/04/2006	Baseline Inspections
1, 2, 3	IP 7111121	Safety System Design and Performance Capability		08/14/2006	08/18/2006	Baseline Inspections
1, 2, 3	IP 7111121	Safety System Design and Performance Capability		08/21/2006	08/25/2006	Baseline Inspections

This report does not include INPO and OUTAGE activities.
 This report shows only on-site and announced inspection procedures.

Electronic distribution by RIV:

Regional Administrator (**BSM1**)

DRP Director (**ATH**)

DRS Director (**DDC**)

DRS Deputy Director (**KMK**)

Senior Resident Inspector (**GXW2**)

Branch Chief, DRP/D (**TWP**)

Senior Project Engineer, DRP/D (**JFD**)

Team Leader, DRP/TSS (**RLN1**)

RITS Coordinator (**KEG**)

V. Dricks, PAO (**VLD**)

W. Maier, RSLO (**WAM**)

C. Gordon (**CJG**)

DRS Branch Chiefs (**LJS, MPS1, REL, NFO**)

S. Richards, Chief, NRR/DIPM/IIPB (**SAR**)

M. Case, Deputy Dir. for Inspection and Programs (**MJC**)

B. Sheron, Associate Dir. for Project Licensing and Technical Analysis (**BWS**)

T. Bergman, Chief, ROPMS, OEDO (**TAB**)

H. Berkow, Director, LPD4, NRR/DLPM (**HNB**)

D. Collins, Chief, PDIV-2, NRR/DLPM (**DXC1**)

M. Fields, NRR Project Manager (**MBF1**)

SISP Review Completed: BSM ADAMS: Yes No Initials: BSM
 Publicly Available Non-Publicly Available Sensitive Non-Sensitive

S:\DRP\DRPDIR\MIDCYCLE 2005\PV.wpd

RIV:C:DRP/D	D:DRS	D:DRP	DRA	RA
TWPruett	DDChamberlain	ATHowell III	TPGwynn	BSMallett
/RA/	KMKennedy for		<u>BSM</u>	<u>BSM</u>
8/23/05	8/25/05	8/26/05	8/ /05	8/26/05

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax