05/29/2009 10:01:12 Page 97 of 226

Document Types: IR, LER From 01/01/2008 to 12/31/2008

U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21

Average for Selected Dockets: 35

	Facility Name: Limerick 1 Docket (050- 00352)		
etails	Department	Work Type	Docket/Report
luman-System Interface & Environmnt / IR			
70 - HSI or information availability / quality LTA	O - Operations	O - Control Room Ops	050-00352/2008-002
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
rocedures & Reference Document / IR			
11 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00352/2008-002
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
roblem Identification & Resolution / IR			
40 - Problem not completely or accurately identified	M - Mechanical	T - Testing	050-00352/2008-009
42 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00352/2008-002
46 - Evaluation LTA	M - Mechanical	T - Testing	050-00352/2008-009
46 - Evaluation LTA	O - Operations	O - Control Room Ops	050-00352/2008-002
48 - Action not yet started or untimely	F - Fuel Handling	R - Refueling	050-00352/2008-002
Number of Items for this Docket: 5 Percent of Total for this Docket: 31			
Vork Planning & Practices / IR			
85 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00352/2008-002
85 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00352/2008-003
86 - Failure to take action / meet requirements	F - Fuel Handling	R - Refueling	050-00352/2008-002
86 - Failure to take action / meet requirements	M - Mechanical	T - Testing	050-00352/2008-009
86 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00352/2008-003
90 - Failure to stop work / non-conservative decision making	F - Fuel Handling	R - Refueling	050-00352/2008-002
Number of Items for this Docket: 6			
Percent of Total for this Docket: 38			
Vork Planning & Practices / LER			
86 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00352/2008-001-00
86 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00352/2008-001-00
96 - Independent verification / plant tours LTA	O - Operations	O - Control Room Ops	050-00352/2008-001-00
Number of Items for this Docket: 3 Percent of Total for this Docket: 19			