

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 20

National Average: 46

2x National Average: 92

National Median: 23

Average for Selected Dockets: 20

Facility Name: Beaver Valley 1 Docket (050- 00334)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
173 - Physical conditions LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2009-003
Number of Items for this Docket: 1 Percent of Total for this Docket: 5			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00334/2009-003
Number of Items for this Docket: 1 Percent of Total for this Docket: 5			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	S - Specialized task force	W - Assessment	050-00334/2008-009
142 - Operating experience (OE) review LTA	S - Specialized task force	W - Assessment	050-00334/2008-009
143 - Tracking / trending LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2009-008
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00334/2008-009
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2009-003
146 - Evaluation LTA	G - Engineering	G - Design	050-00334/2009-003
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00334/2009-008
Number of Items for this Docket: 7 Percent of Total for this Docket: 35			
Work Planning & Practices / IR			
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2009-003
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2009-003
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00334/2009-008
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00334/2009-003
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00334/2009-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00334/2009-003
Number of Items for this Docket: 6 Percent of Total for this Docket: 30			
Oversight / LER			
130 - Inadequate suprevison / command and control	P - Procedure Writers	P - Procedure Dev	050-00334/2009-001-00
Number of Items for this Docket: 1 Percent of Total for this Docket: 5			

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 20

National Average: 46

2x National Average: 92

National Median: 23

Average for Selected Dockets: 20

Facility Name: Beaver Valley 1 Docket (050- 00334)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	O - Operations	S - Surveillance	050-00334/2009-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 5			
Work Planning & Practices / LER			
187 - Action implementation LTA	P - Procedure Writers	P - Procedure Dev	050-00334/2009-001-00
189 - Recognition of adverse condition / questioning attitude LTA	P - Procedure Writers	P - Procedure Dev	050-00334/2009-001-00
196 - Independent verification / plant tours LTA	P - Procedure Writers	P - Procedure Dev	050-00334/2009-001-00
Number of Items for this Docket: 3			
Percent of Total for this Docket: 15			
Total Items for this Docket: 20			
