

R. Van Houten, "Fuel Rod Failure as a Consequence of Departure from Nuclear Boiling or Dryout, NUREG-0562 (1979) Fig. 2-A



R. Van Houten, "Fuel Rod Failure as a Consequence of Departure from Nuclear Boiling or Dryout, NUREG-0562 (1979) Fig. 2-B



Ring compression tests with preoxidised Zr1%Nb and Zircaloy-4 claddings