NRC FORM 591X PART 3
(5-2002)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE	2. NRC/REGIONAL OFFICE
Department of the Army **Electronics Command AMSEL-SF-RER** REPORT NUMBER(S)	**Region I** **475 Allendale Road** **King of Prussia, PA 19406-1415**

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-29741	29-01022-14	October 28 & 29, 2003

6. INSPECTION PROCEDURES USED	7. INSPECTION FOCUS AREAS
87126 & TI-2800-032	03.01 Through 03.07

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTACT	4. TELEPHONE NUMBER
03160	3	Craig S. Goldberg	732-427-3112

[X] Main Office Inspection — Next Inspection Date: _____

[ ] Field Office _____

[ ] Temporary Job Site _____

PROGRAM SCOPE

The management organizational structure is as described in the licence application - no changes have been made since the last inspection with the exception of the appointment of a new RSO. Two Assistant Radiation Safety Officers and the RSO take an active part in the day to day implementation of the program. The licensee uses RAM in Mobile VACIS devices for the detection of contraband. The licensee also possesses RAM, which is used for optical coating on thermal imaging devices and for instrument calibration and testing. The Ram can be used at the facility and at temporary job sites any where in the United States. The RSO maintains a list of persons designated as authorized users who have been trained as described in letters dated 6-28-02 and 08-10-01.

Management appears to provide direct support to the safety program, and all administrators seem knowledgeable of the NRC Rules and Regulations. The inspector confirmed by a document review that all requires annual audits of the safety program have been completed in 2002 and 2003.

The inspector verified by a document review and discussions with the RSO that the Radiation Safety Committee has been meeting at the required frequencies in 2002 and 2003

A review of the regional record system indicate that the license reported an event on 07-23-01 to the NRC. During this inspection, the inspector examined the licencee's follow up actions, and no violations were identified.

A tour of the facility by the inspector determined that it was as described in the license application - no changes were made since the last inspection. Security is maintained by a guard force in conjunction with a badge system. Access to the Ram is limited to only authorized individuals.

The inspector determined by a document review that all required leak tests and physical inventories were being conducted as required. No violations were identified.

During the course of the inspection, the contents of NRC TI-2800-032 were discussed, and no concerns were identified by the licensee.