RPV Head 12 RFO Inspection Results



- 61 - No leakage identified
- 4 - Evaluated not to have sufficient gap to exhibit leakage
- 3 - Insufficient gap with leaking flange
- 5 - Nozzle obscured by boron
- 6 - Nozzle obscured by boron with leaking flange
- - Newly affected, since 11 RFO, by leaking flange(s)

D10
31

- Noticed in 11RFO
- Noticed in 12RFO
- Repaired in 12RFO