3/11/02

RPV Head ~~12~~ 13 RFO Inspection Results

Per Andrew, the hilited were leakers fixed during 12RFO



13 RFO

- (61) - No leakage identified
- (4) - Evaluated not to have sufficient gap to exhibit leakage
- (3) - Insufficient gap with leaking flange
- (5) - Nozzle obscured by boron
- (6) - Nozzle obscured by boron with leaking flange
- (●) - Newly affected, since 11 RFO, by leaking flange(s)

D10
31

- Noticed in 11RFO
- Noticed in 12RFO
- Repaired in 12RFO