APPENDIX A

NOTICE OF VIOLATION

Department of the Army
Washington, DC 20012
License No. 08-01738-02

Docket No. 30-1317

Based on the results of an NRC inspection conducted on December 19 & 20, 1979 it appears that certain of your activities were not conducted in full compliance with NRC regulations and the conditions of your license as indicated below:

A. Condition 23 of your license requires that licensed materials be possessed and used in accordance with statements, representations and procedures contained in your application dated June 18, 1974.

Item 5 of Supplement D of the application dated June 18, 1974 requires that surveys be performed on all incoming packages.

Contrary to this requirement, as of the date of the inspection, December 20, 1979 no surveys were performed on incoming packages between January 9, 1979 and December 12, 1979.

This is an infraction.

B. 10 CFR 20.201(b), "Surveys", requires you to make surveys such as may be necessary for you to comply with all sections of Part 20.

Contrary to this requirement, as of December 20, 1979, you failed to make such surveys as were necessary to assure compliance with 10 CFR 20.106, "Concentrations in effluents to unrestricted areas", a regulation that limits the average yearly concentration of iodine-125 in air discharged to unrestricted areas. Specifically, no evaluations were made of the concentrations of radioactive materials in the effluent air discharged from a hood where millicurie quantities of iodine-125 were processed at varied intervals.

This is an infraction.

C. 10 CFR 20.401(b) requires that you maintain records showing the results of surveys that you made to assure compliance with 10 CFR 20.201(b).

Contrary to this requirement, as of December 20, 1979, you failed to maintain records of the contamination surveys that you performed subsequent to decontamination of areas.

This item is a deficiency.

W/4

OFFICE ►						
SURNAME ►						
DATE ►						