NRC FORM 591M PART 1
(10-2003)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:	2. NRC/REGIONAL OFFICE
Gateway Geotechnical, LLC 208 Chesterfield Industrial Blvd. Chesterfield, MO 63005 REPORT 2007-001	REGION III US NUCLEAR REGULATORY COMMISSION 2443 WARRENVILLE ROAD, SUITE 210 LISLE, ILLINOIS 60532

3. DOCKET NUMBER(S)	4. LICENSEE NUMBER(S)	5. DATE(S) OF INSPECTION
030-37320	24-32630-01	August 27, 2007

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

[X] 1. Based on the inspection findings, no violations were identified.

[ ] 2. Previous violation(s) closed.

[ ] 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ **Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):**

[ ] **4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.**
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Ed Kulzer	E. J. Kulzer	Sept 5, 2007

NRC FORM 591M PART 3
(10-2003)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE	2. NRC/REGIONAL OFFICE
Gateway Geotechnical, LLC REPORT 2007-001	Region III

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-37320	24-32630-01	August 27, 2007

6. INSPECTION PROCEDURES USED	7. INSPECTION FOCUS AREAS
87124	03.01 - 03.07

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM	2. PRIORITY	3. LICENSEE CONTACT	4. TELEPHONE NUMBER
03121	5	Kathy Wurtz	636.532.7747

[x] Main Office Inspection — Next Inspection Date: August 2012

[ ] Field

[ ] Temporary Job Site

PROGRAM SCOPE

This was an intial inspection of activities performed under the license.

The licensee is a small engineering firm that employs five individuals. The licensee possesses one Humboldt 5001 moisture density gauge, for use daily/weekly during the construction season (May-November) for soils engineering projects. The licensee does not perform any service or maintenance activities on its gauge; these services are performed by the manufacturer. Currently, the licensee employs two authorized gauge users who have completed manufacturers training. The licensee stores the gauge in a locked and labeled room in the licensee's facility located in Chesterfield, Missouri.

Performance Observations

At the time of this inspection, the gauge was not in use. The operator possessed required shipping papers which contained all appropriate information and were accessible in the transport vehicle. The operator demonstrated an adequate level of understanding of emergency and handling procedures during interviews. The inspector had an authorized user demonstrate security during transport and noted no problems. The inspector performed independent and confirmatory radiation measurements which indicated similar results as noted in the licensee's survey records.