NRC FORM 591M PART 3
(10-2003) 10 CFR 2.201

**Docket File Information**

**U.S. NUCLEAR REGULATORY COMMISSION**

# SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

| 1. LICENSEE | 2. NRC/REGIONAL OFFICE |
|---|---|
| General Electric Company<br>REPORT NUMBER(S) 2008-001 | **Region III**<br>**2443 Warrenville Road, Suite 210**<br>**Lisle, IL 60532** |

| 3. DOCKET NUMBER(S) | 4. LICENSE NUMBER(S) | 5. DATE(S) OF INSPECTION |
|---|---|---|
| 030-06709 | 48-00337-05 | 4/7 and 11/2008 |

| 6. INSPECTION PROCEDURES USED | 7. INSPECTION FOCUS AREAS |
|---|---|
| 87124 | 3.01 - .07 |

**SUPPLEMENTAL INSPECTION INFORMATION**

| 1. PROGRAM CODE(S) | 2. PRIORITY | 3. LICENSEE CONTACT | 4. TELEPHONE NUMBER |
|---|---|---|---|
| 3225 | 5 | Tracy Gale – RSO | 518-686-4572 |

[X] Main Office Inspection — Next Inspection Date: 4/2013

[ ] Field Office

[ ] Temporary Job Site Inspection

**PROGRAM SCOPE**

**The licensee is a service contractor which handles Gd-153 at hospitals as part of the hospital's PET scanning program. The Gd-153 are used as line sources and point sources for PET. The licensee has service contractors, working out of their residences, perform service calls as needed. The licensee has approximately 900 employees that can perform service under the license. Service operations do not including taking possession of the Gd-153 sources nor transportation. NOTE: The radiation safety officer works out of NY but can be reached from the Wisconsin facility.**

**Performance Observations**

**The inspector reviewed a selected sample of records including training records, dosimetry records and survey meter calibration records.; no abnormal issues were identified. The inspector interviewed the radiation safety officer and several technicians that perform service under the license; each individual had a sufficient amount of knowledge to ensure the safe use of licensed material. The inspector could not perform a field inspection as none was available during the inspection.**