TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401

5N 157B Lookout Place

86 APR 10 A11:5

April 7, 1986

WBRD-50-391/84-39

U.S. Nuclear Regulatory Commission
Region II
Attention: Dr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Dr. Grace:

WATTS BAR NUCLEAR PLANT UNIT 2 - FAILURE OF AN ERCW PUMP SHAFT - WBRD-50-391/84-39 - SECOND SUPPLEMENTAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector P. E. Fredrickson on August 29, 1984 in accordance with 10 CFR 50.55(e) as NCR W-195-P. Our last report was submitted on January 29, 1985. This constitutes our second supplemental report.

As discussed with Bob Carroll on February 20, 1986, the date of August 1, 1985 for installation of the rebuilt unit 2 ERCW pump shafts was not met. Three of the four pumps have been repaired but the fourth has been delayed by material delivery schedules. We will complete repairs to the fourth pump before unit 2 fuel load.

This item has been closed for unit 1 (WBRD-50-390/84-44) in Inspection Report 50-390,391/85-08.

If there are any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

for R. L. Gridley
Manager of Licensing

cc: Mr. James Taylor, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8604160501 860407
PDR ADOCK 05000391
S PDR

1/0 IE27